

Brown, Maxey G, EMNRD

To: CSSwan@manhattanpetroleum.com
Cc: Macquesten, Gail, EMNRD
Subject: Caudill 33 #1 API# 30-025-37804

Connie,

I was talking with Gail Macquesten and passed on that the pit has been filled and returned to natural contour. We checked the well file and found that Chris Williams had denied the chart sent in for the pressure test. The chart indicated a loss over 10% in the 30 minutes of testing. I also noticed that a 3000# chart was used. Rule 203 requires 1000# spring in the recorder and chart to match. In order to satisfy the TA requirements we will need to retest or repair the problem to satisfy the Agreed Compliance Order. I received a phone call that during the test a thunder storm with lighting, hail and wind popped up, could have been part of the pressure decline on the chart??

Please give me a call and we can set up a time to witness the test.

Thanks,
Maxey G. Brown
575-393-6161 ext 107 office
575-370-3179 cell

Maxey G Brown
Scan to file