

2 10 70 PB	
Submit 2 Copies To Appropriate Discrete Page 10 7000 State of New Mexico Office	Form C-103
District 1 1625 N. French Dr., Hobbs, NMR 224	WELL API NO. 20 2027
District II	WEEL ATTNO: 30-025-20007
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Sonto Fo. NIM 87505	STATE FEE A
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Off & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	J.A. Åkens
1. Type of Well: XOil Well Gas Well Other	8. Well Number 8
2. Name of Operator Chesapeake Operating, Inc.	9. OGRID Number 147179
3. Address of Operator P.O. Box 18496	10. Pool name or Wildcat
Oklahoma City, OK 73154-0496	Oil Center; Blinbrey
4. Well Location	
Unit Letter W : 889' feet from the South line and 2289' feet from the East line	
Section 3 Township 21S Range 36E NMPM County 1	
11. Elevation (Show whether DR, RKB, RT, GR, etc. 3558' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS. COMMENCE DR	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	——————————————————————————————————————
OTHER: \times \text{ Location is ready for OCD inspection after P&A} \times \text{ Location is ready for OCD inspection after P&A} \times \text{ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.}	
☐ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
✓ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has	hoon algored of all junk tugch flow lines and
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	duction equipment and junk have been removed
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
non-retrieved flow lines and pipelines.	
• •	
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE Sinda Weeks TITLE Reg. Compliance Spe	DATE 09/09/2008
TYPE OR PRINT NAME Linda Weeks E-MAIL: linda.weeks@chk	.com PHONE: (405)879-6854
For State Use Only	
APPROVED BY:	DATE 10/02/08