

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd. Aztec, NM 87410
District IV
1220 S St Francis Dr. Santa Fe, NM
87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

May 27, 2004

RECEIVED

OCT 20 2008

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

HOBBS (11)

WELL API NO. 30-025-33242
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2148
7. Lease Name or Unit Agreement Name Caprock Maljamar Unit (14578)
8. Well Number 242
9. OGRID Number 8041
10. Pool name or Wildcat Maljamar Grayburg San Andres (43329)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Forest Oil Corporation

3. Address of Operator
707 17th Street, Suite 3600, Denver, Colorado

4. Well Location

Unit Letter: K 1330 feet from the South line and 1330 feet from the West line
Section 28 Township 17S Range 33E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4103' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Pump Repair ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Pump Repair

2/1/08 - RU PU unhung unit head, LD PR, unset pmp POH pmp & rods, pmp had scale, S.I. well SION.

2/4/08 - RU paraffin knife made two runs to 2000' clean tbq, RD paraffin knife, pick up rebuilt pmp 2" x 1/2 x 1 3/4 x 20' w/GA 10' x 1" 1/2. 1" x 3/4 pin pony rod, 102 - 3/4 rods, 78 - 7/8 rods, 2 - 2' x 7/8 subs, 4', 4', 2' x 7/8 subs, PR 22' x 1" 1/4, pmp had scale, plunger would go halfway on pmp, GA had scale too. Hang unit head space pmp, turn unit on, good pmp action, left unit running, couldn't RD - too windy. Send sample of scale to chem.. man. SION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐; a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Kelly Harris

TITLE Regulatory Tech

DATE 10-6-08

Type or print name Kelly Harris

E-mail address: kdharris@forestoil.com

Telephone No. 303-812-1676

For State Use Only

APPROVED BY: [Signature]

TITLE PETROLEUM ENGINEER

DATE OCT 23 2008

Conditions of Approval (if any):