

**RECEIVED**  
 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Avenue, Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. Stephens Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-141  
 Revised October 10, 2003

Submit 2 Copies to appropriate  
 District Office in accordance  
 with Rule 116 on back  
 side of form

### Release Notification and Corrective Action

30-025-31173

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <i>Buckeye Disposal</i>	Contact <i>JIM SAYRE</i>
Address	Telephone No. <i>393-8352</i>
Facility Name <i>CBM #1</i>	Facility Type <i>Disposal</i>
Surface Owner <i>Pace McNeil</i>	Mineral Owner
Lease No.	

#### LOCATION OF RELEASE

Unit Letter <i>P</i>	Section <i>24</i>	Township <i>19S</i>	Range <i>37E</i>	Feet from the <i>467</i>	North/South Line <i>S</i>	Feet from the <i>467</i>	East/West Line <i>E</i>	County <i>LCA</i>
-------------------------	----------------------	------------------------	---------------------	-----------------------------	------------------------------	-----------------------------	----------------------------	----------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE

Type of Release <i>Water + Residue</i>	Volume of Release	Volume Recovered
Source of Release <i>Busted Hose</i>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
*High Pressure Hose busted spraying water + residue on location*

Describe Area Affected and Cleanup Action Taken.\*  
*On pad inside containment berm Roustabout crew to repair hose vacuum truck to pick up fluid*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>J D Sayre</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>J D SAYRE</i>	Approved by District Supervisor: <i>Tommy Hill</i>	
Title:	Approval Date: <b>OCT 24 2008</b>	Expiration Date:
E-mail Address:	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>10-24-08</i> Phone: <i>393-8352</i>		

\* Attach Additional Sheets If Necessary