OCT 0 9 2008

P/A'd. OK TO RELEASE, MAB 10/14/2008

Submit 2-Copies To Appropriate District State of New-Mexico	general and the second bearing of the second
Office District I District I Laboratory Labo	October 25, 2007
1625 N Franching, Albert M. 24 INCLUDE CONVENTION DISTRICTION DIST	WELL API NO (25 27270)
1301 W; Grand 'Ave'; 'Artesia, 'NM 88210 CHYOTE GUNSERVATION DIVISION CSP	5. Indicate Type of Lease, a creation 1
District III 1220 South St. Francis Dr.	STATE STATE
District IV 1220 S St Francis Dr , Santa Fe, NM	6. State Oil & Gas Lease No.
87505	VB-464
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Carp State
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 1
2. Name of Operator	9. OGRID Number
	013837
3. Address of Operator P.O. Box 960 Artesia, NM 88211-0960	I 0. Pool name or Wildcat
4. Well Location /	Hume Queen West/Wildcat Grayburg
Unit Letter P 990 feet from the South line and 990 feet from the East	st line
Section 23 Township 16S Range 33E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Da	ata.
	EQUENT REPORT OF.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	
_ 5	
OTHER: All pits have been remediated in compliance with OCD rules and the terms of the Opera	ready for OCD inspection after P&A
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in	concrete. It shows the
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER QUA	RTER/OHARTER LOCATION OR
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has be	een cleared of all junk, trash, flow lines and
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) h	I level.
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produc	tion equipment and junk have been removed
from lease and well location.	•
All metal bolts and other materials have been removed. Portable bases have been remove to be removed.)	d. (Poured onsite concrete bases do not have
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) N non-retrieved flow lines and pipelines.	MAC. All fluids have been removed from
non-retrieved now fines and piperines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE Jeny W. Shenel TITLE Production Clerk	DATE 10/08/08
TYPE OR PRINT NAME Jerry W. Sherrell E-MAIL: jerrys@mackenergy	/corp.com PHONE: (575)748-1288
For State Use Only	
APPROVED BY:	
Conditions of Approval (if any):	DATE_10/14/2 <i>00</i> 8