AECEWE

P/A'd. OK TO RELEASE. 12/2/2008 MUB.

Submit 2 Con COVA 2 rogia 2008t	State of New Me		Form C-103
Energy, Minerals and Natural Resources 625 N Energy Minerals and Natural Resources OIL CONSERVATION DIVISION		October 25, 2007 WELL API NO.	
1301 W. Grand Ave., Artesia, NM 88210	Artesia, NM 88210 OIL CONSERVATION DIVISION		30-005-10519
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE ☐ FEE ☒
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	20 S. St. Francis Dr., Santa Fe, NM		5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Cat San Andres Unit
1. Type of Well: Oil Well Gas Well Other			8. Well Number CSAU 4
2. Name of Operator Cano Petro of New Mexico, Inc.		9. OGRID Number 248802	
3. Address of Operator		10. Pool name or Wildcat	
801 Cherry Street, Unit 25 Suite 3200, Fort Worth, Texas 76102		Cato; San Andres	
4. Well Location			
Unit Letter I: 1980 feet from the			•
		County Chaves	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4105-KB			
12. Check Appropriate Box to India		Report or Other I	Data
NOTICE OF INTENTION TO: SUBS			SSEQUENT REPORT OF: ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR			
	TIPLE COMPL	CASING/CEMEN	
OTHER:	. п	✓ Location is r	eady for OCD inspection after P&A
☐ All pits have been remediated in comp	liance with OCD rules and t	he terms of the Ope	erator's pit permit and closure plan.
Rat hole and cellar have been filled an	d leveled. Cathodic protecti	ion holes have been	properly abandoned.
A steel marker at least 4" in diameter a	nd at least 4' above ground	level has been set in	n concrete. It shows the
OPERATOR NAME, LEASE N	AME, WELL NUMBER,	API NUMBER, QI	UARTER/QUARTER LOCATION OR
UNIT LETTER, SECTION, TO			ON HAS BEEN WELDED OR
PERMANENTLY STAMPED O	N THE MARKER'S SUR	FACE.	4
	as possible to original grou	and contour and has	been cleared of all junk, trash, flow lines and
other production equipment.		4 C41-1-	11 1
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
			fuction equipment and junk have been removed
from lease and well location.			,
All metal bolts and other materials have to be removed.)	been removed. Portable ba	ises have been remo	oved. (Poured onsite concrete bases do not have
All other environmental concerns have	been addressed as per OCI	rules.	
Pipelines and flow lines have been aba			NMAC. All fluids have been removed from
non-retrieved flow lines and pipelines.			
When all work has been completed, return t inspection has to be made to a P&A location	his form to the appropriate land because it does not meet the	District office to sch	nedule an inspection. If more than one penalty may be assessed.
SIGNATURE SUTULIA	TITLE A	Replator	y Covalination 11/20/08
TYPE OR PRINT NAME (INDY	CHAVEZ E-MAIL:	CINOS VOCA	NO PETYO. CAMONE: 8/7-698-09
For State Use Only	M.I.) MX	
APPROVED BY:	11 Dieg) LINOUTH	DATE 12/2/2008
Conditions of Approval (if any):		***	DATE

COMPLIANCE OFFICER