RECEIVED

1625 N French Dr , Hobbs, NM 88240 <u>District II</u> 1301 W Grand Avenue, Artesia, NM 88210

1000 Rio Brazos Road, Aztec, NM OBBSOCD

1220 S St. Francis Dr., Santa Fe, NM 87505

District I

District III

State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 July 21, 2008

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office.

For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Pit, Closed-Loop System, Below-Grade Tank, or
Proposed Alternative Method Permit or Closure Plan Application
Type of action. Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method
Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances
Operator: Cimarex Energy Co. of Colorado QGRID#: 162683
Address: P.O. Box 140907: Irving TX 75014-0907
Facility or well name: Midway 17 Federal No. 1
Facility or well name: Midway 17 Federal No. 1 API Number: 30-005-29034 OCD Permit Number: P1-00850
U/L or Qtr/Qtr E Section 17 Township 15S Range 31E County: Chaves
Center of Proposed Design: Latitude 33.017588N Longitude 103.851102 W NAD: \(\sqrt{1927} \sqrt{1983}
Surface Owner: Nederal State Private Tribal Trust or Indian Allotment
2. Pit: Subsection F or G of 19.15.17.11 NMAC
Temporary Drilling Workover
Permanent Emergency Cavitation P&A
Lined Unlined Liner type. Thicknessmil LLDPE HDPE PVC Other
String-Reinforced
Liner Seams: Welded Factory Other Volume: bbl Dimensions: L x W x D
Closed-loop System: Subsection H of 19.15.17.11 NMAC
Type of Operation: 🔲 P&A 🔀 Drilling a new well 🔲 Workover or Drilling (Applies to activities which require prior approval of a permit or notice of

Liner Seams Welded Factory Other	
Below-grade tank: Subsection I of 19.15.17.11 NMAC	_
Volume:bbl Type of fluid:	
Tank Construction material:	
Secondary containment with leak detection Wisible sidewalls, liner, 6-inch lift and automatic overflow shut-off	
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Other	
Liner type: Thicknessmıl	

Alternative Method:

Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

☑ Drying Pad ☐ Above Ground Steel Tanks ☐ Haul-off Bins ☐ Other

☐ Lined ☐ Unlined Liner type: Thickness 20 mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify	hospital,
7. Netting: Subsection E of 19 15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other Monthly inspections (If netting or screening is not physically feasible)	
8. Signs: Subsection C of 19.15.17.11 NMAC 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers Signed in compliance with 19.15.3 103 NMAC	
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s) Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	office for
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accept material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the approx office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to dry above-grade tanks associated with a closed-loop system.	opriate district approval.
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No ☐ NA
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo, Satellite image	☐ Yes ☐ No ☐ NA
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within the area overlying a subsurface mine - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	Yes No
Within an unstable area. - Engineering measures incorporated into the design, NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No
Within a 100-year floodplain FEMA map	☐ Yes ☐ No

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19 15 17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15 17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19 15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15 17.9 NMAC and 19.15.17 13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number.
Previously Approved Design (attach copy of design) API Number. Previously Approved Operating and Maintenance Plan API Number: (Applies only to closed-loop system that use above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19.15 17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15 17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17 11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Laner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19.15 17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15 17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15 17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: (19 15 17 13 Instructions: Please indentify the facility or facilities for the disposal of liquids, drilling fluids and drill cuttings. Use attachment if facilities are required.	.D NMAC) f more than two
Disposal Facility Name: Controlled Recovery Inc. Disposal Facility Permit Number: NMOCD R916	6/NMED DP818
Disposal Facility Name: Disposal Facility Permit Number:	
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used for future se Yes (If yes, please provide the information below) \(\subseteq \) No	
Required for impacted areas which will not be used for future service and operations: Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19.15.17.13 NMA Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC	AC .
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sou provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate disconsidered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Just demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	trict office or may be
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - 1WATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site, Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	Yes No
Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
Within an unstable area. - Engineering measures incorporated into the design, NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No
Within a 100-year floodplain FEMA map	☐ Yes ☐ No
On-Site Closure Plan Checklist: (19 15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure piby a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19 15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19.15 17.11 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15 17.13 NMAC	
Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17 13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cann Soil Cover Design - based upon the appropriate requirements of Subsection H of 19 15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19 15.17.13 NMAC	ot be achieved)

Operator Application Certification: I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief.
Name (Print) Title:
Signature: Date
e-mail address Telephone:
20. OCD Approval: Permit Application (including closure plan) Closure Plan (only) CCD Conditions (see attachment)
OCD Representative Signature: Deckhay Lewing Approval Date: 01/14/09
OCD Representative Signature: Deckhoy Leving Approval Date: 01/14/09 Title: Environmental Engineer OCD Permit Number: P1-00850
Closure Report (required within 60 days of closure completion): Subsection K of 19.15.17.13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed.
☐ Closure Completion Date:Reseed Spring 2009
Closure Method: Waste Excavation and Removal On-Site Closure Method Alternative Closure Method Waste Removal (Closed-loop systems only) If different from approved plan, please explain.
23. Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: Instructions: Please indentify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more than two facilities were utilized.
Disposal Facility Name: Disposal Facility Permit Number:
Disposal Facility Name Disposal Facility Permit Number:
Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations? Yes (If yes, please demonstrate compliance to the items below) No
Required for impacted areas which will not be used for future service and operations: Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique
24 Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check
mark in the box, that the documents are attached.
Proof of Closure Notice (surface owner and division)
Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits)
☐ Confirmation Sampling Analytical Results (if applicable)
Waste Material Sampling Analytical Results (required for on-site closure) □ Discoord Facility Name and Results (required for on-site closure)
 ✓ Disposal Facility Name and Permit Number ✓ Soil Backfilling and Cover Installation
☑ Re-vegetation Application Rates and Seeding Technique
Site Reclamation (Photo Documentation) On-site Closure Location. Latitude Longitude NAD: □1927 □ 1983
v
Operator Closure Certification:
I hereby certify that the information and attachments submitted with this closure report is true, accurate and complete to the best of my knowledge and belief. I also certify that the closure complies with all applicable closure requirements and conditions specified in the approved closure plan.
Name (Print) Dorsey Rogers Title: Field Superintendent
Signature:
e-mail address: dorseyrogers@aol.com Telephone: 575-200-6105







4311 Monica Lane, Carlsbad, NM 88220

Phone 575-236-6012

Fax 575-236-6063

Cell 575- 361-3217

bandr@pvtnetworks.net

December 13, 2008

Cimarex Energy Co. P.O. Box 140907 Irving Texas 75014-0907

Re:

Cimarex Energy Co.

Midway 17 Federal No. 1 – Final Drying pad Closure

Midway 17 Federal No. 1

API: 30-005-29034

Sec 17-T-15S-R-31E

Depth to Ground Water: 50' O.C.D.

Planned Analytical Testing: Chlorides, BTEX, TPH Primary Land Use: Ranching and Oil & Gas Production

Pursuant to Paragraph (1) of Subsection D of 19.15.17.13 NMAC of the New Mexico Oil Conservation District of the State of New Mexico regulatory requirement for drying pad closure, please accept the following documentation for final closure of the drying pad for the aforementioned location.

All drill cuttings were transported to Controlled Recovery, Inc. of Hobbs, New Mexico (Permit number NMOCD R 9166 / NMED DP818). Upon transferring all drying pad contents to C.R.I., field tests were performed on the soil within in the confines of the original drying pad. The analytical results of Chloride delineation, BTEX 8021B/602/8260B/624, and TPH 8015 GRO/DRO/TVHC of the impacted material are attached.

Soil samples were collected, prepared, and packaged per EPA guidelines and forwarded to Trace Analysis in Lubbock, Texas for official analytical testing. Please find the official analytical results attached hereto.

Soil backfill and cover design was done to meet appropriate requirements of subsection H of 19.15.17.13 NMAC. This included covering sites existing grade by applying one foot of existing topsoil to establish growth. The entire disturbed are was then contoured to prevent ponding of water and erosion of cover material.

Site reclamation was done to meet appropriate requirements of subsection G of 19.15.17.13 NMAC. This included reclaiming areas associated with the drying pad to a safe and stable condition that blends with surrounding undisturbed area and restoring surface area to conditions that existed prior to oil and gas operations.

Re-vegetation will be done to meet appropriate requirements of subsection I of 19.15.17.13 NMAC. This includes seeding all areas disturbed and associated with the drying pad. Seeding will be done in spring of 2009 to achieve better growth.

Order of events:

- 1. Received approval to excavate from O.C.D. on August 11, 2008
- 2. Began Removing mud August 18, 2008
- 3. Finished removing mud August 22, 2008
- 4. Phoenix Environmental performed field samples and continued digging until September 30, 2008.
- 5. Covered and contoured affected area with dozer on October 27, 2008.

Sampling-Performed by Phoenix Environmental


Sample #1-SW-33°01'03.6" -N-103°51'04.1"-W Sample #2-NW-33°01'04.1"-N -103°51'04.2"-W Sample #3-Center-33°01'03.9"-N-103°51'03.9"-W Sample #4-NE-33°01'04.2"-N-103°51'03.6"-W Sample #5-SE-33°01'03.7"-N-103°51'03.7"-W Background Sample-33°01'05.5"-N-103°51'03.3"-W

Final Depth: 1' Below Liner N.E and S.E. quad. 3' Below liner on the N.W. and S.W. quads

Please review the attached documentation and contact me at 575-361-2132 with any questions or concerns.

Sincerely,

Rayland VanNatta B&R Trucking



Report Date: October 1, 2008

API 30-005-29034

Work Order: 8092929 Midway 17 Fed. #1 Page Number: 1 of 2 UL-E-Sec. 17, T15S-R31E

Summary Report

Dorsey Rogers Cimarex 207 S. Mesa Carlabad, NM, 88220 Report Date: October 1, 2008

Work Order: 8092929

Project Location: UL-E-Sec. 17, T15S-R31E Project Name: Midway 17 Fed. #1 Project Number: API 30-005-29034

			Date	Time	Date
Sample	Description	Matrix	Taken	Taken	Received
174960	Southwest 1/4 @ 3'	soil	2008-09-26	10:00	2008-09-29
174961	Northwest 1/4 @ 3'	soil	2008-09-26	10:15	2008-09-29
174962	Center @ 3'	soil	2008-09-26	10:30	2008-09-29
174963	Northeast 1/4 @ 1'	soil	2008-09-26	10:45	2008-09-29
174964	Southeast 1/4 @ 1'	soil	2008-09-26	11:00	2008-09-29
174965	Background @ 0-6"	soil	2008-09-26	11:30	2008-09-29

			BTEX		MTBE	TPH 418.1	TPH DRO	TPH GRO
	Benzene	Toluene	Ethylbenzene	Xylene	MTBE	TRPHC	DRO	GRO
Sample - Field Code	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)
174960 - Southwest 1/4 @ 3'	< 0.0100	< 0.0100	< 0.0100	< 0.0100		<10.0	<50.0	<1.00
174961 - Northwest 1/4 @ 3'	< 0.0100	< 0.0100	< 0.0100	< 0.0100	į	<10.0	<50.0	<1.00
174962 - Center @ 3'	<0.0100	< 0.0100	< 0.0100	< 0.0100		<10.0	<50.0	<1.00
174963 - Northeast 1/4 @ 1'	<0.0100	< 0.0100	< 0.0100	< 0.0100	İ	<10.0	<50.0	<1.00
174964 - Southeast 1/4 @ 1'	< 0.0100	< 0.0100	< 0.0100	< 0.0100		<10.0	<50.0	<1.00
174965 - Background @ 0-6"	< 0.0100	< 0.0100	< 0.0100	< 0.0100		<10.0	<50.0	<1.00

Sample: 174960 - Southwest 1/4 @ 3'

Param	Flag	Result	Units	RL
Chloride		38.6	mg/Kg	3.25

Sample: 174961 - Northwest 1/4 @ 3'

Param	Flag	Result	Units	RL
Chloride		<32.5	mg/Kg	3.25

TraceAnalysis, Inc. • 6701 Aberdeen Ave., Suite 9 • Lubbock, TX 79424-1515 • (806) 794-1296

This is only a summary. Please, refer to the complete report package for quality control data.

Report Date: Octo API 30-005-29034	ber 1, 2008	Work Order: 8092929 Midway 17 Fed. #1	Page Number: 2 of UL-E-Sec. 17, T15S-R31	
Sample: 174962	- Center @ 3'			,
Param	Flag	Result	Units	RL 3.25
Chloride		<32.5	mg/Kg	
Sample: 174963	- Northeast 1/4 @ 1'			
Param	Flag	Result	Units	RL
Chloride		167	mg/Kg	3.25
Sample: 174964	- Southeast 1/4 @ 1'			
Param	Flag	Result	Units	RL
Chloride		149	mg/Kg	3.25
Sample: 174965	- Background @ 0-6"			
Param	Flag	Result	Units	RL
Chloride		46.0	mg/Kg	3.25

TraceAnalysis, Inc. • 6701 Aberdeen Ave., Suite 9 • Lubbock, TX 79424-1515 • (806) 794-1296

This is only a summary. Please, refer to the complete report package for quality control data.

2008-11-17 18:48

Page 4

11/13/2008 17:13 `:

5053919687

LAB Order	F 10 #	509	2989	

Page

of_

		6701 Aberdeen Averue, Suite 9 5002 Ba Lubbock, Tearen 79424 Tel (806) 794-1296 Tel: Fax (806) 794-1298 Fax 1 (800) 378-1296								nd, Texas 79703 El Pr (432) 689-6301 Tel (432) 689-6313 Fax						Peo lei (9 8x (t Sunset Rd., Suite E 1990, Texas 78922 (915) 585-3443 r (915) 585-4944 (888) 588-3443					8808 Camp Bowne Blvd: West, Suits 180 Ft. Worth, Texas 76118 Tex (817) 201-5260 Fax (817) 560-4336												
Address:	LL SZS-391-9685 241 Fax 8: 525-391-9687 E-mail: EAHOUSE @LEAKO.NET								<u> </u>	ANALYSIS REQUEST (Circle or Specify Method No.)																								
Contact Person											١		60108/2007	-			-	-									Jard							
invoice to: (If different from	store Cimpre	X														54	(C3		49 6010	Se Hg													m stan	
Project 8: API Project Location	T= 30-065-25 n (including state):	9030	4					<u> </u>	ال	WA	Y_	17	F	المتألي	/ 8280B /	9/80	2 2 S		P 8 F	5			The verse plans	3631	3				N				ent fro	
UL-6 - 6	SEC 17- TISS- R3	12				24	mpler	0	<u>U</u>	Z,	<u>ን</u>	Ł			02 / 8:	7 826			200	6	1 25			/ 624 8770	3	808		1	2				differ	
		ERS	2	- 1	MATR	TRIX			METHOD			SAMPLING			8021B / 802	7 60	ž Š	625	As Ba	2 2 2	/Otarbi	9 9 9		380	3	81A	I	E 1	5				Lime	
LAB (CAB USE) CHLY	FIELD CODE	* CONTAINERS	Volume / Amount	WATER	AIR	SCUDGE	HCI	HNO,	H ₂ SO.	ZE CE	NONE		DATE	THATE	MTBE 802	BIEX 802 1B3 602 / 8260B / 624	TPH 418 DY TX1006 / TX1009 EX(C35) TPH 8015 GRO JORGH TVHC	PAH 8270C /	Total Metals Ag As	TCLP Wetals Ag As Ba Cd Cr Po	TCLP Semi Volatiles	TCLP Pesticides	RCI	GC/MS Vol. 82808 / 624	PCR's ROR7 /	Pesticides 8081A / 608	BOD, TSS, pH	Moisture Cor	,		employers to tourisement the second	A STATE OF THE PARTY OF THE PAR	Turn Around Time if different from standard	Hold
74100 So	withwast to 3'	14	Q.	7	4					X		-	9264	10:10	-	N 7 A	۲,	}		Ť	f		7		+			-	×	1	十	\dashv		=
90 10	erhwest 4e3	1 (X	*					X			1	10:15		×	×,								3			•	4			\Box		
16066	will @ 3'	1		*	-11				\perp	X				10:30		-	××				L					_			₹					
2512.00000000000000000000000000000000000	entleaste i	1			4		\bot	_	+	K	-	_	1	10:45	L		< X		4	_	1	igspace	4	\perp	\downarrow	1			4	\sqcup		_	\dashv	
労の主の主義が	ckgrowd@ 0-6"	1	1	<u> </u>	-	+	+	-	\dashv	X	_	-	1,	11:00	-	1	XX		\dashv	+	+	$\left \cdot \right $	4	+	+	+	-	7	<u> </u>	\dashv	\rightarrow	\dashv	\dashv	
		 	+	+		+			+	+	╫		-	1130	-	1	7			+	╁╴		\dagger	+	+	+	-		╁	H	+	\dashv	-	
									1	\top			 		┢	-	\dagger			十	1		\dagger	+	+	+			+	$\dagger \dagger$	$\neg \dagger$	\dashv	1	_
			\Box																						I	I			I					
	<u> </u>		4	-		4			_	_	_						_			\downarrow	_		\dashv	\perp	\perp	\perp	L							_
Refingulation	Company: Date;	Time	-	Rece	plyed	bv:		Ampe	my:		Date	<u> </u>	Time	Tor	D0.5		12.00				 		MA.	D I G		L			\perp	Ш			_	
DUL.		and the second								ONLY 2-Day Rush																								
Relinquished by	Received by: Company: Bate: Time: Ten								np	Dry Wei									Weig	M Basis Required														
Relinquished by		Page 1	ived O	7	N	company: Date: Time:							np".	TRRP Report Required Check If Special Reporting Limits Are Needed																				
Submittel of sem	ples constitutes agreement to Tes	ms and C	ent.	ices	listed	on re	Verse	side	of (C	977107	• (7	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	7		=												