District I District I 1625 N French Dr., Hobbs, NMRECEIVED Energy Minerals and Natural Resources 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 8746 3 0 2008 1220 S St Francis Dr., Santa Fe, MOBBSOCD

State of New Mexico Department Oil Conservation Division 1220 South St. Francis Dr.

Santa Fe, NM 87505

For temporary pits, closed-loop systems, and

below-grade tanks, submit to the appropriate NMOCD District Office.

For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application

Type of action. Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method
Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.
Operator Cimarex Energy Co. OGRID #.
Address: P.O. Box 140907, Irving TX 75014-0907
Facility or well name: Enterprise 11 State Com No. 1
API Number: 30-005-28002 OCD Permit Number: P1-20849
U/L or Qtr/Qtr M Section 11 Township 15S Range 31E County: Chaves
Center of Proposed Design. Latitude 33.024104 N Longitude 103.799344 W NAD: 1927 1983
Surface Owner Federal State Private Tribal Trust or Indian Allotment
Pit: Subsection F or G of 19.15 17.11 NMAC Temporary: Drilling Workover Permanent Emergency Cavitation P&A Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other String-Reinforced Liner Seams: Welded Factory Other Volume: bbl Dimensions L x W x D
Below-grade tank: Subsection I of 19.15.17.11 NMAC Volumebbl Type of fluid: Tank Construction material: Secondary containment with leak detection Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off Visible sidewalls and liner Visible sidewalls only Other Liner type: Thickness mil HDPE PVC Other
5. Alternative Method:

Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval

Fencing: Subsection D of 19 15.17 11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify	hospital,
Netting: Subsection E of 19 15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other Monthly inspections (If netting or screening is not physically feasible)	
Signs: Subsection C of 19 15 17 11 NMAC 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers Signed in compliance with 19.15 3 103 NMAC	
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	office for
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accept material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the approoffice or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying above-grade tanks associated with a closed-loop system.	priate district pproval.
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS, Data obtained from nearby wells	☐ Yes ☐ No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No ☐ NA
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No ☐ NA
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Ycs ☐ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within 500 feet of a wetland - US Fish and Wildlife Wetland Identification map; Topographic map, Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No
Within a 100-year floodplain FEMA map	☐ Yes ☐ No

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17 9 NMAC
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.
Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API Number: or Permit Number:
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.
Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 Situng Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15.17.9 NMAC and 19.15.17 13 NMAC
Previously Approved Design (attach copy of design) API Number:
Previously Approved Operating and Maintenance Plan API Number:(Applies only to closed-loop system that use
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15 17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
Waste Excavation and Removal Closure Plan Checklist: (19.15 17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. ☐ Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC ☐ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15.17 13 NMAC ☐ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) ☐ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19 15.17.13 NMAC ☐ Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC ☐ Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

Waste Removal Closure For Closed-loop Systems That Utilize Above Groun Instructions: Please indentify the facility or facilities for the disposal of liquids facilities are required.		
facilities are required. Disposal Facility Name:Controlled Recovery Inc.	Disposal Facility Permit Number. NMOCD R9166	NMED DP818
Disposal Facility Name:	Disposal Facility Permit Number:	
Will any of the proposed closed-loop system operations and associated activities ☐ Yes (If yes, please provide the information below) ☐ No		
Required for impacted areas which will not be used for future service and operate. Soil Backfill and Cover Design Specifications based upon the appropriate Re-vegetation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection	te requirements of Subsection H of 19 15.17.13 NMAC n I of 19.15.17.13 NMAC	
17. Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC		
Instructions: Each siting criteria requires a demonstration of compliance in the provided below. Requests regarding changes to certain siting criteria may request considered an exception which must be submitted to the Santa Fe Environment demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC	ire administrative approval from the appropriate distr al Bureau office for consideration of approval. Justi	ict office or may be
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS, Database search; USG	ata obtained from nearby wells	Yes No
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Database search;	ata obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS, Database search; US	nta obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other s lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	ignificant watercourse or lakebed, sinkhole, or playa	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or churchy Visual inspection (certification) of the proposed site; Aerial photo, Satellia		☐ Yes ☐ No
Within 500 horizontal feet of a private, domestic fresh water well or spring that le watering purposes, or within 1000 horizontal feet of any other fresh water well or - NM Office of the State Engineer - iWATERS database; Visual inspection	spring, in existence at the time of initial application.	Yes No
Within incorporated municipal boundaries or within a defined municipal fresh was adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality, Written approximately.	•	☐ Yes ☐ No
Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map, Vis	ual inspection (certification) of the proposed site	☐ Yes ☐ No
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Minim	ng and Mineral Division	☐ Yes ☐ No
Within an unstable area - Engineering measures incorporated into the design; NM Bureau of Geolo Society, Topographic map	gy & Mineral Resources; USGS, NM Geological	☐ Yes ☐ No
Within a 100-year floodplain FEMA map		☐ Yes ☐ No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of a by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements Construction/Design Plan of Burial Trench (if applicable) based upon the Construction/Design Plan of Temporary Pit (for in-place burial of a drying Protocols and Procedures - based upon the appropriate requirements of 19. Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Disposal Facility Name and Permit Number (for liquids, drilling fluids and Soil Cover Design - based upon the appropriate requirements of Subsection Re-vegetation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the ap	equirements of 19.15.17 10 NMAC of Subsection F of 19.15 17.13 NMAC appropriate requirements of 19.15.17.11 NMAC pad) - based upon the appropriate requirements of 19.15.17.13 NMAC equirements of Subsection F of 19.15.17.13 NMAC of Subsection F of 19.15.17.13 NMAC drill cuttings or in case on-site closure standards cannot H of 19.15.17.13 NMAC in I of 19.15 17.13 NMAC	15.17.11 NMAC

Form C-144 Oil Conservation Division Page 4 of 5

19,		
Operator Application Certification: I hereby certify that the information submitted with this application is	true, accurate and complete to the	he best of my knowledge and belief
Name (Print):	<u>-</u>	
Signature:	Date:	***************************************
e-mail address Tele	ephone:	
OCD Approval: Permit Application (including closure plan)		
OCD Representative Signature: Leffrey Liking		Approval Date: 01/14/09
OCD Representative Signature: Decofficer Likeing Title: Environmental Engineer	OCD Permit Num	Approval Date: <u>01/14/09</u> Aber: <u>PJ~0D849</u>
Closure Report (required within 60 days of closure completion): Instructions: Operators are required to obtain an approved closure The closure report is required to be submitted to the division within to section of the form until an approved closure plan has been obtained	plan prior to implementing any 60 days of the completion of the	closure activities and submitting the closure report. closure activities. Please do not complete this
		pletion Date:October 29,2008
22. Closure Method: Waste Excavation and Removal ☐ On-Site Closure Method ☐ If different from approved plan, please explain.	☐ Alternative Closure Method	Waste Removal (Closed-loop systems only)
23. Closure Report Regarding Waste Removal Closure For Closed-loc Instructions: Please indentify the facility or facilities for where the l two facilities were utilized.	op Systems That Utilize Above liquids, drilling fluids and drill of	Ground Steel Tanks or Haul-off Bins Only: cuttings were disposed. Use attachment if more than
Disposal Facility Name.	Disposal Facility P	ermit Number:
Disposal Facility Name:		ermit Number:
Were the closed-loop system operations and associated activities performed Yes (If yes, please demonstrate compliance to the items below)	ormed on or in areas that will not	
Required for impacted areas which will not be used for future service of Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique	and operations:	
Closure Report Attachment Checklist: Instructions: Each of the fark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude	te closure)	
	Longitude	NAD· □1927 □ 1983
Operator Closure Certification: I hereby certify that the information and attachments submitted with the belief. I also certify that the closure complies with all applicable closure.	is closure report is true, accurate re requirements and conditions s	e and complete to the best of my knowledge and specified in the approved closure plan.
Name (Print). Dorsey Rogers	Title:	Field Superintendent
Signature:	Date:	12/23/2008
e-mail address dorseyrogers@aol.com	Telephone:	<u>575-200-6105</u>







4311 Monica Lane, Carlsbad, NM 88220

Phone 575-236-6012

Fax 575-236-6063

Cell 575-361-3217

bandr@pvtnetworks.net

December 13, 2008

Cimarex Energy Co. P.O. Box 140907 Irving Texas 75014-0907

Re: Cimarex Energy Co.

Enterprise 11 State Com No. 1 – Final Drying pad Closure

Enterprise 11 State Com No. 1

API: 30-005-28002 Sec 11-T-15S-R-31E Depth to Ground Water: 50' O.C.D.

Planned Analytical Testing: Chlorides, BTEX, TPH Primary Land Use: Ranching and Oil & Gas Production

Pursuant to Paragraph (1) of Subsection D of 19.15.17.13 NMAC of the New Mexico Oil Conservation District of the State of New Mexico regulatory requirement for drying pad closure, please accept the following documentation for final closure of the drying pad for the aforementioned location.

All drill cuttings were transported to Controlled Recovery, Inc. of Hobbs, New Mexico (Permit number NMOCD R 9166 / NMED DP818). Upon transferring all drying pad contents to C.R.I., field tests were performed on the soil within in the confines of the original drying pad. The analytical results of Chloride delineation, BTEX 8021B/602/8260B/624, and TPH 8015 GRO/DRO/TVHC of the impacted material are attached.

Soil samples were collected, prepared, and packaged per EPA guidelines and forwarded to Trace Analysis in Lubbock, Texas for official analytical testing. Please find the official analytical results attached hereto.

Soil backfill and cover design was done to meet appropriate requirements of subsection H of 19.15.17.13 NMAC. This included covering sites existing grade by applying one foot of existing topsoil to establish growth. The entire disturbed are was then contoured to prevent ponding of water and erosion of cover material.

Site reclamation was done to meet appropriate requirements of subsection G of 19.15.17.13 NMAC. This included reclaiming areas associated with the drying pad to a safe and stable condition that blends with surrounding undisturbed area and restoring surface area to conditions that existed prior to oil and gas operations.

Re-vegetation was done to meet appropriate requirements of subsection I of 19.15.17.13 NMAC. This included seeding all areas disturbed and associated with the drying pad. BLM #2 was hand broadcasted at 20 lbs. per acre

Order of events:

- 1. Received Verbal approval to excavate from O.C.D. on August 4, 2008
- 2. Began Removing mud August 8, 2008
- 3. Finished removing mud August 18, 2008
- 4. Phoenix Environmental performed field samples and continued digging until August 20, 2008.
- 5. Covered and contoured affected area with dozer on October 29, 2008.

Sampling-Performed by Phoenix Environmental


Sample #1-SW-33°01'27.5" -N-103°47'58.0"-W Sample #2-NW-33°01'28.0"-N -103°47'57.9"-W Sample #3-Center-33°01'27.8"-N-103°47'57.5"-W Sample #4-NE-33°01'28.0"-N-103°47'57.3"-W Sample #5-SE-33°01'27.5"-N-103°47'57.5"-W Background Sample-33°01'28.1"-N-103°47'56.7"-W

Final Depth: 1' Below Liner

Please review the attached documentation and contact me at 575-361-2132 with any questions or concerns.

Sincerely

Rayland VanNatta B&R Trucking



Report Date: October 29, 2008

API 30-005-28002

Work Order: 8102703 Enterprise 11 St. Com. 1

Page Number: 1 of 2 UL-M, Sec. 11, T15S-R31E

Summary Report

Dorsey Rogers Cimarex 207 S. Mesa

Carlsbad, NM, 88220

Report Date: October 29, 2008

Work Order: 8102703

Project Name: Project Number:

Project Location: UL-M, Sec. 11, T15S-R31E Enterprise 11 St. Com. 1 API 30-005-28002

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
177355	Northwest 1/4 @ 2'	soil	2008-10-23	13:00	2008-10-24
177356	Southwest 1/4 @ 2'	soil	2008-10-23	13:15	2008-10-24
177357	Center @ 2'	soil	2008-10-23	1 3:30	2008-10-24
177358	Northeast 1/4 @ 2'	soil	2008-10-23	13:45	2008-10-24
177359	Southeast 1/4 @ 2'	soil	2008-10-23	14:00	2008-10-24
177360	Background @ 0-6"	soil	2008-10-23	14:30	2008-10-24

			BTEX		MTBE	TPH 418.1	TPH DRO	TPH GRO
	Benzene	Toluene	Ethylbenzene	Xylene	MTBE	TRPHC	DRO	GRO
Sample - Field Code	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/×s)	(mg/Kg)	(mg/Kg)
177355 - Northwest 1/4 @ 2'	< 0.0100	< 0.0100	< 0.0100	< 0.0100		<10.0	<50.0	<1.00
177356 - Southwest 1/4 @ 2'	< 0.0100	< 0.0100	< 0.0100	< 0.0100	l	<10.0	<50.0	<1.00
177357 - Center @ 2'	< 0.0100	< 0.0100	< 0.0100	< 0.0100	i	<10.0	<50.0	<1.00
177358 - Northeast 1/4 @ 2'	<0.0100	< 0.0100	< 0.0100	< 0.0100		<10.0	<50.0	<1.00
177359 - Southeast 1/4 @ 2'	<0.0100	< 0.0100	< 0.0100	< 0.0100	1	<10.0	<50.0	<1.00
177360 - Background @ 0-6"	< 0.0100	< 0.0100	< 0.0100	< 0.0100	1	<10.0	<50.0	<1.00

Sample: 177355 - Northwest 1/4 @ 2'

Param	Flag	Result	Units	RL
Chloride		138	mg/Kg	3.25

Sample: 177356 - Southwest 1/4 @ 2'

Param	Flag	Result	Units	RL
Chloride		99.5	mg/Kg	3.25

TraceAnalysis, Inc. • 6701 Aberdeen Ave., Suite 9 • Lubbock, TX 79424-1515 • (806) 794-1296 This is only a summary. Please, refer to the complete report package for quality control data.

2008-11-17 18:35 PHOENIX ENVIRON 5053919687 Page 2

Report Date: October 29, 2008 API 30-005-28002		2008 Work Order: 8102703 Enterprise 11 St. Com. 1		Page Number: 2 of 2 UL-M, Sec. 11, T15S-R31E			
Sample: 177357 - Center @ 2'							
Param	Flag	Result	Unita	RL			
Chloride		136	mg/Kg	3.25			
Sample: 177358	- Northeast 1/4 @ 2'						
Param	Flag	Result	Units	RL			
Chloride		163	mg/Kg	3.25			
Sample: 177359	- Southeast 1/4 © 2 '		• .				
Param	Flag	Result	Units	RL			
Chloride		224	mg/Kg	3.25			
-	- Background @ 0-6"						
Param	Flag	Result	Units	RL			
Chloride		86.4	mg/Kg	3.25			

TraceAnalysis, Inc. • 6701 Aberdeen Ave., Suite 9 • Lubbock, TX 79424-1515 • (806) 794-1296
This is only a summary. Please, refer to the complete report package for quality control data.

2008-11-17 18:36

PHOENIX ENVIRON

5053919687

0007/CT/TT

2000 TECCAC

TraceAnaly email: lab@traceana	-	Inc.	6701 Aberdeen Avenue S Lubbock, Texas 7942 Tel (806) 794-1296 Fex (806) 794-1298 1 (800) 378-1296	24 Midlen	un Street. Suite d. Texas 7970 132) 589-6301 432) 689-6313	3 El Paso, Taxas 798 Tel (915) 585-3443	22 Ft. Worth, Texas 78116 Tel (817) 201-5260 4 Fax (817) 560-4336
Company Name: Plozu. x Emiranmen	34 L		575-391-96	85		ANALYSI	S REQUEST
Address: (Street, City, Zip) PD BOX 1556 1666		Fex ا 8 کے دیدا					cify Method No.)
Contact Person:	محت	E-17	Altodor CC2		(22)	Hg Hg	standard
Invoice to: (If different from above) CAA72EX					1624 624 5 EM(C:	Pb Se Hg	
API = 30-005 - 1800	<u>ک</u>		Ject Name: SUTERPIZISS_11	1 STEON!	1 602 / 8260B / 624 802 / 8260B / 624 1005 / TX1005 EXI / DRO / TVHC	8 5	A : 42 5 5 A : 42 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
Project Location (including state): ULM - 5 & G // - 7 (55 - 123):			ripler Signetture:	Ste	826 7 X / O	6 Cd Ch 3c Ba Cd Ch 3c Cd Ch 3c Cd	1608 1 408 1
		MATRIX	PRESERVATIVE METHOD	SAMPLING	80218 / 602 / 0218 / 802 / 1 / TX1005 5 GRO / DR	625 Ag As Ba C Ag As S S S Ses Mes	Vol 8 908 81A/6 H Imme if
LAB W.SE) ONLY	# CONTAINERS Volume / Amount	WATER SOIL AIR 3LUDGE	HCI HNO, H,SO, NaOH ICE	DATE	MTBE 80218 / 602 / 82608 / 624 BTEX 80218 / 602 / 82608 / 624 TPH 418.1 / TX1005 / TX1005 EXI(C35) TPH 8015 GRO / DRO / TVHC	PAH 8270C / 625 Total Metals Ag As Ba Cd Gr Pb Se Hg 6010B/200 / TCLP Metals Ag As Be Cd Cr Pb Se Hg TCLP Volatiles TCLP Semi Volatiles TCLP Semi Volatiles TCLP Restoides RCI GC/MS Vol. 8280B / 624	GCMS Sem. Val. 8270C / 626 PCB's 8082 / 608 Pesticides 8081 A / 608 BOD. TSS, pH Moishure Content C. L. C. L.
7350 1-Abathurst 4@ 2'	1 1/2	X		73.00 1.00	ХУX	┤┈┋╸┋┈┆┈┝╸┩╶┡╸┋ ╌ ╏	
26 2-Southwasi 4@2		R		115	××y		
50 3-4 UNI @ 2'	1 1	K	T X	130	* * /		X
4- NORTH EAST 4@ 2'		À		1:45	XXX		
559 5-South 1 457 4@2'	1	K	X	2:00	××>		×
6- BALKELOUNDED-6"	1	X	X	الآيا الم	XX7	(
				1			
11							
Relinguished by: Compeny: Dete:	Time: /458	Received by:	Company: Date:			AB USE REMARK	Day Rush
Relinquisher by: Company: Date:	Times.	Received by:	Company: Data:	Time: Ter	18398		ry Weight Basts Required
Relinquished by: Company: Date:	Time:	Received by:	Company: Date: The 10	Time: Te	mp [°] c:		RRP Report Required heck If Special Reporting muts Are Needed
Submittal of samples constitutes agreement to Ten	ms and Con				Carrier #	Carry en	

LAB Order ID#

8102703

Page