



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Field Inspection Program

"Preserving the Integrity of Our Environment"

26-Feb-09

CONOCO PHILLIPS
ATTN:KENNY KIDD/ RUDY QUIROZ
HC 60 BOX 66
LOVINGTON, NM 88260

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

EAST VACUUM (GSA) UNIT No.005

H-32-17S-35E

30-025-02965-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/11/2009	Bradenhead	Sylvia Dickey	Yes	No	6/1/2009	iSAD0905738382
Comments on Inspection: OPERATOR NEEDS TO VERIFY THE SURFACE AND INTERMEDIATE STRINGS OF CASING. BRADENHEAD TEST SHOWS 320# OF PRESSURE AND SALT WATER SHOW ON THE SURFACE OR INTERMEDIATE STRING OF CASING. IN ADDITION, THE UNION BETWEEN THE TUBING AND CASING ON THE OFFSIDE OF WELLHEAD EQUIPMENT NEEDS TO BE FIXED AND SECURED. ****OPERATOR IN VIOLATION OF NMOC Rule 115. *****NMOC WILL NOT ADDRESS SURFACE VIOLATION, UNTIL STRING IS VERIFIED BY OPERATOR.*****						

EAST VACUUM (GSA) UNIT No.003


N-27-17S-35E

30-025-32058-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/10/2009	Bradenhead	Sylvia Dickey	Yes	No	5/16/2009	iSAD0905740204
Comments on Inspection: TOP FLANGE ON WELLHEAD IS LEAKING PER OPERATOR HAS TURNED IN FOR REPAIRS. ****OPERATOR IN VIOLATION OF NMOC Rule 115*****						

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.


Sincerely,



Hobbs OCD District Office
COMPLIANCE OFFICER

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas


EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER	017H15554612	US POSTAGE
	\$0.590	
	02/26/2009	
	Mailed From 88240	

CONOCO PHILLIPS
ATTN:KENNY KIDD/ RUDY QUIROZ
HC 60 BOX 66
LOVINGTON, NM 88260

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



017H15554612

\$0.590

02/26/2009

Mailed From 88240

US POSTAGE

CONOCO PHILLIPS CO.
ATTN: REG.DEPT.-CELESTE DALE
3300 N. 'A' STR., BLDG 6 #247
MIDLAND, TX 79705