

NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor Joanna Prukop Cabinet Secretary

Mark E. Fesmire, P.E. Director Oil Conservation Division

Field Inspection Program "Preserving the Integrity of Our Environment"

26-Feb-09

CONOCO PHILLIPS ATTN: KENNY KIDD/ RUDY QUIROZ HC 60 BOX 66 LOVINGTON, NM 88260

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPEC	TION .	DETAIL	SECTION

Yes

EAST VACUUM	(GSA)	UNIT	No.005
-------------	-------	------	--------

Bradenhead

H-32-17S-35E

No

30-025-02965-00-00

Inspection Type Inspection Date

Inspector

Sylvia Dickey

*Significant Violation? Non-Compliance?

Corrective Action Due By: 6/1/2009

Inspection No.

iSAD0905738382

Comments on Inspection:

OPERATOR NEEDS TO VERIFY THE SURFACE AND INTERMEDIATE STRINGS OF CASING. BRADENHEAD TEST SHOWS 320# OF PRESSURE AND SALT WATER SHOW ON THE SURFACE OR INTERMEDIATE STRING OF CASING. IN ADDITION, THE UNION BETWEEN THE TUBING AND CASING ON THE OFFSIDE OF WELLHEAD EQUIPMENT NEEDS TO BE FIXED AND SECURED. ****OPERATOR IN VIOLATION OF NMOCD RULE 115.****NMOCD WILL NOT ADDRESS SURFACE VIOLATION. UNTIL STRING IS

VERIFIED BY OPERATOR.*****

EAST VACUUM (GSA) UNIT No.003

N-27-17S-35E

30-025-32058-00-00

Inspection

02/11/2009

Type Inspection

Inspector

*Significant Violation? Non-Compliance? Corrective

Inspection No.

Date 02/10/2009 Bradenhead

Sylvia Dickey

Yes

No

Action Due By: 5/16/2009

iSAD0905740204

Comments on Inspection:

TOP FLANGE ON WELLHEAD IS LEAKING PER OPERATOR HAS TURNED IN FOR

REPAIRS. ****OPERATOR IN VIOLATION OF NMOCD RULE 115****

Oil Conservation Division * 1625 N. French Drive * Hobbs, New Mexico 88240 Phone: 505-393-6161 * Fax: 505-393-0720 * http://www.emnrd.state.nm us

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Hobbs OCD District Office
COMPLIANCE OFFICER

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.


*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



017H15554612 \$0.590 02/26/2009 Mailed From 88240 US POSTAGE

CONOCO PHILLIPS ATTN:KENNY KIDD/ RUDY QUIROZ HC 60 BOX 66 LOVINGTON, NM 88260 EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



017H15554612 \$0.590 02/26/2009 Mailed From 88240

US POSTAGE

CONOCO PHILLIPS CO. ATTN: REG.DEPT.-CELESTE DALE 3300 N. 'A' STR., BLDG 6 #247 MIDLAND, TX 79705