

MAR U 6 ZOUS

Submit 2 Copies To Appropriate District BDSUCU State of New Mexico HOBB:	Form C-103
District 1 Energy, Minerals and Natural Resources	October 25, 2007
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-33105
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name FOSTER
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	POSTER
PROPOSALS.) 1. Type of Well: Xillian Gas Well Cother	8. Well Number 5
2. Name of Operator DAVID H. ARRINGTON OIL & GAS INC	9. OGRID Number 5898 -
3. Address of Operator PO BOX 2071 MIDLAND, TX 79702	10. Pool name or Wildcat
TO BOX 20/1 MIDLAND, 1X /9/02	Monument Abo
4. Well Location	1.20.00.00.00
Unit Letter O: 990 feet from the S line and 1650 feet from the E line	
Section 34 Township 19S Range 36E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3622' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PAND A	
TEMPORARILY ABANDON	
OTHER: Location is ready for OCD inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBÉR, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	r ¹
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location (s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, pro-	
from lease and well location.	auction equipment and junk have been removed
All metal bolts and other materials have been removed. Portable bases have been removed.	oved. (Poured onsite concrete bases do not have
to be removed.)	
X All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from	
non-retrieved flow lines and pipelines.	5.
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one	
inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
The same of the sa	
SIGNATURE WAS TITLE ENGINEER TECH	DATE <u>03/04/2009</u>
TYPE OR PRINT NAME DEBBIE FREEMAN E-MAIL: DEBBIE@ARRINGTONOIL.COM PHONE: (432)682-6685	
For State Use Only	
APPROVED BY: Wah Whytake TITLE COWD. Off	DATE 3/9/2004
Conditions of Approval (if any):	