Submit 3 Copies To Appropriate District Office	State of Nev		Form C-103
District I	Energy, Minerals and	Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 3002529869
District II 1301 W Grand Ave , Artesia, NM 882 N			5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 A District IV	PR 114 2019 South St.	Francis Dr.	STATE 🛠 FEE 🗵
District IV	Santa Fe, N	M 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NMHC 87505	BBSOCD PAGE 1	OF 3	
	ICES AND REPORTS ON W		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR USE "APPLIPROPOSALS.)			VE RODDY /
1. Type of Well: X Oil Well	Gas Well Other		8. Well Number
2. Name of Operator			9. OGRID Number
KEVIN O BUTLER & ASSOCIA	TES, INC.		12627
3. Address of Operator PO BOX 1171, MIDLAND, TEXA	AS 79702		10. Pool name or Wildcat 36330 KNOWLES DEVONIAN N
4. Well Location			,
			50feet from theEASTline /
Section 23	Township 16S Ran		
	11. Elevation (Show whethe 3697' GR 3719' KB	r DR, RKB, RT, GR, etc.,	
	,		
12. Check	Appropriate Box to Indica	ate Nature of Notice.	Report or Other Data
			•
NOTICE OF IN PERFORM REMEDIAL WORK	_		SEQUENT REPORT OF:
TEMPORARILY ABANDON X	PLUG AND ABANDON CHANGE PLANS		
PULL OR ALTER CASING	MULTIPLE COMPL		
DOWNHOLE COMMINGLE			_
OTHER:		OTHER.	
	leted operations (Clearly stat	OTHER:	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.		•	5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
V.E. RODDY Workover		Condition of Approx	val: Notify OCD Hobbs
V.L. RODDI Workover		office 24 hours price	or to running MIT Test & Chart
12/27/2007	1	\	Test & Chart
12,2,72007			· · · · · · · · · · · · · · · · · · ·
8:00 AM Rig on the locat	ion. Started to rig up ar	nd the deadman bro	oke off at the ground. Waiting on
the anchor truck to put in ar	nother one.	.a the dedantal pro	one on at the ground. Waiting on
•			
9:00 AM Breaking off the	wellhead and the tubir	ng parted at the slip	s. Called Double R Pipe to deliver
100 jts of 2-1/8" tubing to fish	the tubing with. Instal	I BOP. Centrilift or	location @ 10:30 AM, left @ 2:30
PM.			, 3
11:00 AM The anchor true	ck showed up. Rigged ι	up the unit.	
0.00 004 - 71 - 4.11			
2:00 PM The tubing show	ved up, picked up the fi	shing tools and sta	rted picking up the tubing.
2.00 DM - Fielding 4-1	according Of the Control		
3:00 PM Fishing tools showed up. Started in the hole.			
5:00 DM Cought the field	المسالية المسامة مسا	mina and after the	D
5:00 PM Caught the fish and started pulling the pipe out of the hole. Pulled up to the fish and layed down the fishing tools. Put on a 2-1/6" sub and closed the BOP.			
down the naming tools. Put (או a 2-78 SUD and Close	eu ine BOP.	

7:00 PM Shut down.

12/28/2007

6:45 AM Crew started laying down the tubing and Centralift was there with the spool.

3:30 PM Out of the hole with the tubing and started laying down the pump.

6:00 PM Shut down.

Equipment 338 Jts 2-%" Good pipe

7 Jts Bad pipe (bent)
1 jt surface parted
1 Submersible pump

Pipe sent to R&R in Lovington for storage (505) 396-4586

Cable & pump & motor went with Centrilift

Spool: HD78-13069 w/approx 10,200' cable. Centrilift indicated that our type of wellhead (HHS) was notorious for surface shorts. Once equipment on surface, no damage. However, motor was burned.

V.E. RODDY Workover

03/31/05

Disconnect cable, nipple down wellhead, install BOP. RU spooler, POH w tbg & pump. Pulled tight on bottom, like fill around pump. Wind high, blowing tbg on derrick man. SD 1:30 PM

04/01/05

Finish POH w/pump, lay down pump. Send pump and cable to shop. SD Will try to run back tomorrow. Talk to Jason at Centralift at 11:30 AM

04/02/05

Pick up pump and assemble. RU spooler, RIH w/tbg & pump, banding cable, 4 bands per stand, land tbg. 2:00 PM NU well head, hook up cable, check out panel, start up pump. Pump up in 10 min. 3:30 PM SD

1

04/03/05

Rig Down.

- 1) Well Status Request Temporary Abandonment
- 2) Effective 4/09
- 3) Reason Unable to operate in the current condition
- 4) Future Plans Rework and bring into production
- 5) Date of Future Plans 2009

Conditions of Approval (if any):

Spud Date:	Rig Release Date:	
I hereby certify that t	he information above is true and complete to the best of my knowle	dge and belief.
SIGNATURE	TITLE President/Owner I	OATE 4-7-09
Type or print name	KEVIN O BUTLER E-mail address: robie@geedmidland.com	PHONE: 432-682-1178
For State Use Only	DISTRICT 1 SU	PERVISOR
APPROVED BY:	TITLE DISTRICT + O	DATE

No MIT 2009 4-10-2009