
Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	nergy, Minerals and Natural Resources	WELL API NO.
District II	₩ CONSERVATION DIVISION	30-005-00931
1301 W. Grand Ave., Artesia, N District III 1000 Rio Brazos Rd., Aztec, NM 87410		5. Indicate Type of Lease STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Oy Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505 HORSON	:n	303735
SUNDRY NOTICES A (DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)	ND REPORTS ON WELLS DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Rock Queen Unit
1. Type of Well: Oil Well X Gas W	ell 🗌 Other	8. Well Number 86
2. Name of Operator CELERO ENERGY	II, LP	9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, St	e. 1601	10. Pool name or Wildcat
Midland, TX 797	01 、	Caprock Queen
4. Well Location		
Unit Letter E: 1980	feet from the North line and 660	feet from the Westline
Section 36	Township 13S Range 31E	NMPM County Chaves
11. E	levation (Show whether DR, RKB, RT, GR, etc.)	
	· · · · · · · · · · · · · · · · · · ·	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENT	ION TO:	SEQUENT REPORT OF:
	S AND ABANDON ☐ REMEDIAL WOR	
TEMPORARILY ABANDON 🔲 CHAI	IGE PLANS 🔲 COMMENCE DRI	<del>- "</del>
<del></del> -	TIPLE COMPL   CASING/CEMENT	ГЈОВ 🔲
DOWNHOLE COMMINGLE		
OTHER:	☐ OTHER: TA'd	X
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
3/26-4/2/09		
MIRU. TOH w/rods & tbg. TIH w/2 7/8" tbg w/4 3/4" OD tapered mill. Ran to 3015'. End of csg @ 3051'. Ran csg inspection &		
cmt bond logs. Ran CIL from surface to 3039'. Ran CBL from 2300' to 3037'. TOC @ 2480'. Ran & set CIBP @ 3000' per csg inspection log. TIH w/2 7/8" tbg & 5 1/2" pkr. Tested CIBP @ 3000' w/670#. Held okay. Located holes in 5 1/2" csg from 120' to		
157'. Pumped into holes w/1 BPM & 200# pressure. Backed off 5 1/2" csg @ 180'. TOH w/ 178' of csg. found btm jt of csg to have		
split in same. TIH w/180' (4 jts) of 5 1/2", 15.5#, K-55 LT&C csg. Screw into fish @ 180'. Tested csg from surface to 3000'		
w/560#. Held okay. Set slips, installed bell nipple & screw on WH. TIH w/ 2 7/8" tbg open ended to 2977'. TOH. LD tbg. Tied on csg to run integrity test. Would pressure to 600#; leaked off in 200# in 1 min. TIH w/ tbg & pkr. Backed of 5 1/2" csg @ 213' using		
a centralized 160 grain string shot. TOH w/5 jts of 5 1/2" csg & found the btm jt had a split down about 3' from top of it. Replaced it		
w/5 1/2", 15.5#, K-55, LT&C csg (35.20'). Ran total of 5 jts & screwed into fish @ 213'. Tied onto csg & tested same from surface to 3000' w/600# & held okay. Set slips. Welded on bell nipple & installed WH. Tested 5 1/2" csg for the OCD required integrity		
test to 560#. Held okay for 32 mins. RE	welded on bell hippie & installed wh. Tested . Well now TA'd	5 1/2" csg for the OCD required integrity
*Original chart is attached.	, · · · · · · · · · · · · · · · · · · ·	
	This Appro	val of Temporany
Spud Date:	Rig Release Date: Abandonm	val of Temporary ent Expires <u>4-22-2014</u>
I hereby certify that the information above is	true and complete to the heat of my knowledge	and holiof
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Lisa Hun	TITLE Decorleton Analyst	DATE 04/12/2000
	TITLE Regulatory Analyst	DATE <u>04/13/2009</u>
Type or print name <u>Lisa Hunt</u> For State Use Only	E-mail address: <u>LHunt@celeroen</u>	
- 1 / 1 / 1 / ·	JISTRICT 1 SUPER	VISOR APR 2 2 2009
APPROVED BY: Conditions of Approval (if phy):	TITLE TITLE	DATE



Steen Foot Representation for Colore Energy IT C.P.