## Pla'd. OK TO RELEASE. YMUR 4/30/2009

Submit 2 Copies To Appropriate District Office State of New Me		Form C-103 October 25, 2007
District I 1625 N. French Dr., Hobbs, NM 882 10 District II 1301 W. Grand Ave., Artesia, NM 882 10 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM		WELL API NO. 30-005-00856
		5. Indicate Type of Lease STATE FEE X
		6. State Oil & Gas Lease No.
87505  SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Upit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Rock Queen Unit
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other Injection		8. Well Number / 56
2. Name of Operator  CELERO ENERGY II, LP		9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701		10. Pool name or Wildcat Caprock Queen
4. Well Location  Unit Letter F: 1980 feet from the North line and 1980 feet from the West line		
Section 25 / Township 13S Range 31E NMPM County Chaves		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4384' KB		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON		
PULL OR ALTER CASING	CASING/CEMENT	JOB
OTHER:    D   D   Location is ready for OCD inspection after P&A		
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.  A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.  If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.		
△ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)		
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.		
	egulatory Analyst	DATE 04/23/2009
TYPE OR PRINT NAME Lisa Hunt E-MAIL: LHunt@celeroenergy.com PHONE: (432)686-1883		
APPROVED BY: Y ALEXANDER TITLE Conditions of Approval (if any)	ompliance	Officer DATE 04/30/2009