

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr. Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Arriba Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
PAGE 1 OF 2

WELL API NO.  
3000500662  
5. Indicate Type of Lease  
STATE ☒ FEE ☐  
6. State Oil & Gas Lease No.  
B-8664  
7. Lease Name or Unit Agreement Name  
SOUTH CAPROCK QUEEN UNIT  
8. Well Number  
015  
9. OGRID Number  
12627  
10. Pool name or Wildcat  
08550 CAPROCK QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-100) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

KEVIN O BUTLER & ASSOCIATES, INC.

3. Address of Operator

PO BOX 1171, MIDLAND, TEXAS 79702

1. Well Location

Unit Letter: G 1980 feet from the EAST line and 990 feet from the SOUTH line  
Section 30 Township 15S Range 31E NMPM CHAVES County

11. Elevation (Show whether DR, R&B, RT, GR etc.)  
3448' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☒  
PULL OR ALTER CASING ☐ MULTIPLE COMPL. ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: RETURN TO PRODUCTION ☒

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of proposed completion or recompletion.

- Rig doing road repair in order to access with rig and other needed equipment.
- Wells is down up well service equipment, investigate unknown artificial lift failures, repair and return to production.
- Currently steep hill located below the Caprock.
- Investigating the possibility of access to well on the south end by a different road that will not be using the hill
- Roads going down the hills are in very bad shape.
- Rigging up on the well in 2-3 weeks.


Condition of Approval:

OCD requires the Operator to complete a 24 hour production test and submit on form C-104. Request for Allowable before producing this well. Accompanied by Subsequent report of C-103 with dates and what was done, perfs producing from, along with the tubing size and depth

Spud Date


Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE:  TITLE: President/Owner DATE: 5-1-09

Type or print name: KEVIN O BUTLER E-mail address: robie@geogmidland.com PHONE: 432-682-1178

For State Use Only

APPROVED BY:  TITLE: DISTRICT 1 SUPERVISOR DATE: MAY 11 2009