Submit 2 Copies To Appropriate District State 6	of New Me	vico		Form C-103
State	CENED Minerals and Natural Resources		October 25, 2007	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	30-025-34086
301 W. Grand Ave , Artesia, NM 882 MAY JULIE CONSERVATION DIVISION		5. Indicate Type	of Lease	
1000 Rio Brazos Rd., Aztec, NM 8/FILIPA COLLEGE Sonto Fe NIM 27505		STATE CIL 8 C	FEE X	
1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & G	ias Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name of	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Kyte	/
1. Type of Well: \(\sum \) Oil Well \(\sum \) Gas Well \(\sum \) Other			8. Well Number 6	
2. Name of Operator Chesapeake Operating, Inc.			9. OGRID Number	
3. Address of Operator P.O. Box 18496 Oklahoma City, OK 73154-0496			10. Pool name or Wildcat Warren; San Andres, East	
4. Well Location				3105, 2450
		00' feet from the East		/
Section 5/23 Township 20 S Range 38E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3568' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
				EPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORI TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI				ALTERING CASING ' P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN				
OTHER.		M Location is no	- d. f- a OCD ima	anation often DOA
OTHER: \times \text{ Location is ready for OCD inspection after P&A} \times \text{ Location is ready for OCD inspection after P&A} \times \text{ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.}				
X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR				
<u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u> PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)				
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from 				
Pipelines and flow lines have been abandoned in accornon-retrieved flow lines and pipelines.	ndance with	[9.15.9./14.B(4)(b) [NMAC. All fluid	s have been removed from
	l			
When all work has been completed, return this form to the inspection has to be made to a P&A location because it do				
SIGNATURE They Arms	TITLE Se	enior Regulatory Cor	npl. Sp.	_DATE <u>05/26/2009</u>
TYPE OR PRINT NAME Bryan Arrant	E-MAIL:	bryan.arrant@chk.c	com	PHONE: (405)935-3782
For State Use Only		~m.	D.	6/02/2009
APPROVED BY: Water White Conditions of Approval (if any):	TITLE_ <u>(</u>	ones. Othic	er 1ª	"BATE 3/18/2009