



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required – Deadline Enclosed

08-Jun-09

ENERVEST OPERATING L.L.C.

1001 FANNIN ST, STE 800

HOUSTON TX 77002-

LETTER OF VIOLATION - Inactive Well(s)

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that the well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

1. Immediately restore the well(s) to production, injection or disposal as applicable.
2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

IDLE WELL INSPECTION DETAIL SECTION

EBENEZER BBZ STATE 001	E-9-16S-32E	30-025-29780-00-00	Inspection No. iJRH0915938837
Inspection Date:	6/8/2009 10:47:14 AM	Corrective Action Due by: 9/11/2009	
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	John Harrison	No	No
Comments on Inspection:	WELL SIGN INACCURATE, DOES NOT HAVE CURRENT OPERATOR. WELL IS SHUT IN WITH NO PRODUCTION REPORTED IN 17 MONTHS. IDLE WELL RULE 201, TA, PA, OR RETURN TO PRODUCTION.		

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.


Sincerely,

A handwritten signature in black ink, appearing to read "Jack Harrison Co.", with a stylized flourish at the end.

Hobbs OGD District Office

* Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER
017H15554612
\$0.44⁰
06/08/2009
Mailed From 88240
US POSTAGE

ENERVEST OPERATING LLC
1001 FANNIN ST, STE 800
HOUSTON TX 77002