Submit 3 Copies To Appropriate District State of New Mexico Office Energy Minomals and Natural Deserves	Form C-103
District I Energy, Minerals and Natural Resources	Revised May 08, 2003
1625 N. French Dr., Hobbs, NM 87240 District II	WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	<u>30-025-22829</u> 5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505	STATE I FEE
District IV	
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: MALLON "C" STATE
1. Type of Well: Oil Well Image: Second state of the	8. Well No.
2. Name of Operator	9. OGRID Number
GRUY PETROLEUM MANAGEMENT CO. ATTN: DON ALDRIDGE	
3. Address of Operator	10. Pool name or Wildcat
P.O. BOX 140907	LOVINGTON PENN NE
4. Well Location	
Unit Letter <u>A</u> : <u>660</u> feet from the <u>NORTH</u> line and	660 feet from the EAST line
Section 20 Township 16S Range 37E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, e. 3820' - GROUND LEVEL	tc.)
12. Check Appropriate Box to Indicate _l Nature of Notice	Report or Other Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	
PULL OR ALTER CASING DULTIPLE CASING TEST AND COMPLETION CASING TEST AND	ABANDONMENT
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.	give pertinent dates, including estimated date n wellbore diagram of proposed completion
PLEASE CONTACT DAVID EYLER AT 432-687-3033.	D HAVE ANY QUESTIONS OR COMMENTS
Verment . Pull packer & tag commonthes of first .	Kel (E 000 E) squar
of first .	EME DE 6256
	La car
	C1-1E0E620
I hereby certify that the information above is true and complete to the best of my knowledge and belie	f.
SIGNATURE David A. La TITLE A	DATE <u>12/26/03</u>
Type or print name DAVID A. EYLER	Telephone No. 432–687–3033
(This space for State use)	
APPROVED BY Mus Universe TITLE TITLE	diperion DATE 12/30/04

1 .		
Eservin	DATE	12/30/0
<i>v</i>		

Gruy Petroleum Management Company State "C" #1 A.P.I. #: 30-025-22829 Lease Serial #: Field: Lovington Penn NE Location: 660' FNL & 660' FEL, Unit Letter A, Sec. 20, Twp. 16S, Rge. 37E Lea County, New Mexico

Completion Da	te: 1981
Total Depth:	11,658' P.B.T.D.:
Casing Data:	13-3/8" 48# @ 377' w/ 360 sxs Cement circulated to surface.
	8-5/8" 24# & 32# @ 4350' w/ 550 sxs. – TOC = +/-3020'
	5-1/2" 17# & 20# @ 11658' w/ 485 sxs. – TOC = +/- 9060'
Tubing Data:	+/- 7870' 2-3/8" – Top of fish @ +/- 4201'
Rod Data:	+/- 7850' Steel & Fiberglass – Top of fish @???
Open Perfs:	11403'-11484'
Remarks:	Rods, tubing and casing parted 03/96; Pulled +/- 4061 5-1/2" casing; Top of rod/tubing fish @ +/- 4120'; Pulled one joint of casing that had collapsed down on another. Probably another joint of casing looking up in the same condition.

PXA PROCEDURE

- 1) MIRU workover rig, PXA equipment and 4,000' workstring.
- 2) ND wellhead and NU BOP's; PU 8-5/8" CICR & RIH w/ CICR & tubing to 4000'; Set CICR @ 4000' & mix & squeeze a 200 sx. class "C" cmt. plug below CICR; Sting out of CICR & mix & pump a 40 sx. class "C" cmt. plug on top of CICR @ 4000'; Circulate well w/ PXA mud; POOH w/ tbg. standing back 1900' & laying down the balance.
- 3) RUWL & RIH & perf. sqz. holes in 8-5/8" csg. @ 2150'; POOH & RDWL; PU 8-5/8" pkr. & RIH w/ pkr. & tbg. to 1900'; Mix & sqz. a 75 sx. class "C" cmt. plug @ 2050'-2150'(Salt); Rel. pkr. & POOH w/ tbg. & pkr. & WOC; Remove pkr. & RIH w/ tbg. OE & tag top of cmt. plug; POOH w/ tbg. standing back 200' & laying down the balance; RUWL & RIH & perf. sqz. holes in 8-5/8" csg. @ 450'; POOH & RDWL; PU 8-5/8" pkr. & RIH w/ pkr. & tbg. to 200'; Set pkr. & mix & sqz. a 75 sx. class "C" cmt. plug @ 350'-450'(Fresh water); Rel. pkr. & POOH laying down tbg. & pkr.
- 4) RIH / tbg. OE to 63'; Mix & pump a 20 sx. cmt. surf. plug @ 3'-63'. FOOH w/ tubing. PU & RIH w/ 1" tbg. to 63' in 8-5/8" X 13-3/8" annulus; Mix & pump a 20 sx. class "C" cmt. plug @ 3'-63'; POOH w/ 1" string.
- 5) Dig out and cut off well head 3' B.G.L.; Weld steel plate on top of casings & set dry hole marker.
- 8) RDMO rig and PXA equipment. Clean location.



MALLON OIL COMPANY N. E. Lovington State C No. 1

Mar. 18, 1996

RU power swivel and rotate tubing and overshot. Drilled down 9 feet. Stopped making hole at 3507'. RIH with 2-1/4" lead block on sandline. Depth-O-Meter showed top of rods at 3345'. Impression showed fibergless rod body. RIH with 2-6/18" OD Fibergless rod overshot and 40' of barrel on 132 1" rods with 1-5/8" catcher. Stop going at 3337'. Could not catch fish. Pull up hole and go down again. Tag at 3300', could not get back down to 3337', POH. No fish. POH with tubing and overshot. Had approx. 220' of rods inside tubing. Had to cut rods out of tubing with hacksaw. Grapple was plugged solid with fiberglass shaving. SION. Prep rerun overshot on tubing. Dally Cost: \$3645.00

Mar. 19, 1996

RIH 4-11/16" overshot with 2-3/8" grapple, mill control, 4-11/16" overshot extension, on 2-7/8" tubing. Tag fish at 3507'. Pull 80,000# to get fish to start jumping up hole. Hung up 45' up and took 100,000# to pull free. Rie with 4-11/16" oversocket with 2-5/8"-3-1/8" catch, XO, bumper sub, jars, six 3-1/2" DC's, XO (total BHA 196.96'). Tag at 3506'. Suspect parted casing. Could not work overshot into lower casing section. TOOH. TiH with 5-1/2" spear. XO, bumper sub, jars, six 3-1/2" DC's, XO (total BHA 199.23'). Spear into casing at 2289'. Puli 80,000# and set off jars. Casing dragging up hole. Pull all of tubing except for last joint. SIFN. Prep to lay down casing and continue fishing tubing, Dally Cost: \$5170.00

Mar. 20, 1996 Finish POH with BHA. Release spear. RU casing crew and lay down 56 joints of casing. Total of 1857:95! Two joints split over each other approx. 17' and bottom joint split half way up (appears half of casing way inside 5-1/2" casing and other half was outside). Total of 56 joints recovered today and 61-1/2 joints previous total of 117-1/2 joints of 501/2" casing recovered today and 61-1/2 joints previous total of 117-1/2 joints of 501/2" casing recovered today and 61-1/2 joints previous descentions. It is approve to be at 4120.53. RiH with 4-11/16" oversockst with 2-5/8" and 3-1/8" catch. XO, bumper sub, jars, six 3-1/2" DC's, XO (total BHA 196.96"). Could not work overshot into 5-1/2" casing at 4120.53'. POH with tubing and BHA, SDFN. Prep to run 4-3/4" tapered mill to dress off top of 5-1/2" casing Daily Cost: \$3950.00

Mar. 21, 1998 RIH 4-3/4" tapered mill, jars, DC's, XO, and 128 jts of tubing. Tag at 4113'. rig up swivel. Trickla PVV down annulus. Mill down to 4118'. POH. Mill was mushroomed on bottom and wore down on sides of taper. RiH with 4-5/8" shoe, dressed with 3" ID, top bushing with cut rite inside, jars, DC's, XO, and 126 jts of tubing. Tag at 4113'. Rig up swivel. Trickle PVV down tubing. Work into 5-1/2" casing. Tag up at 4118.00'. Began milling, mill down to 4123'. POH. Shoe was worn on bottom, but not on ID or top bushing. SIFN. Prep to run another shoe to trim egged 5-1/2" casing and top of 2-3/8" tubing. Daily Cost: \$8036.00 i,

: •

1

· |

•

.....

ŧ

MALLON OJ, COMPANY N. E. Lovington State C No. 1

			_
			1825' Recovered.
			1825
Mar. 11,	1996	MIRU workover rig. ND well head. TO SDFD.	OH with (Fard Fig rod parted pin break).
	·: ·	Daily Cost: \$412.00	Cum: \$412_00
Mar. 12,		to top of parted FG rod, attempt to uns fiberglass rod parted, tog parted. TOO (parted). Top 5 of me Still Up	ring enchors TOCH with 54 pt of 2-3/5 the set pump, pull rods in tension, top H with 10 more its of 2-3/8" tbg (total 99 its parted: body broak, 8000 tbg with 500% of ; TiH with 4" impression block. Impression
Mar. 13,	1998		rods, 68-7/8" FG rods. TOOH lay down
		rods and tbg. Release rig. SDFD, Daily Cest: \$600.00	Cum: \$3, 378.00
Mar. 14,	, 1996	from Mailon's yard. Set out 2-3/8" tubi	tal delivered 3 sets pipe racks and catwalk ng and old rods. Unload 373 its used 2-7/8" 7-1/16" 3000# tubing spool. Prep to pull 5- Cum: \$5,593.00
Mar. 15	, 1996	install 10" x 3000# BOP, PU 5-1/2" spe 5-1/2" casing at 2297.22', NOTE: 1008 60,000# (45,000# over weight). Had a weight gained. Work pipe, release spe	ar on 75 its 2-7/8" N80 tubing. Tag top of A cosing unaccountable. Pull up to pprox. 1-1/2' of stretch for 45,000# of
Mar. 16,	.1998	showed perfect picture of 5-1/2" casing top of rods to approx. 3278'. Feit light from working into 5-1/2" casing at 2297 grapple for 2-3/8" tubing body. Tag top over fiberglass rods to tubing by rotatin 3491' before tubing tongs got to hot. F	of casing at 2297'. TOH. Lead blocks collar. TIH with 4-1/2" lead block to find contact. POH. Only marks on blocks were ". TIH with 4-11/18" OD overshot with of rods at 3477'. Attempt to work down g tubing and overshot. Worked down to sel confident that rods are going into tubing rel and continue to work down over rods to Cum: \$13,283,00
		· · · · · · · · · · · · · · · · · · ·	

• + •

÷

i

• 1∂1™

MALLON OIL COMPANY

4

State C No. 1

Lovington, NE Field

.

DATE	RODS RECOVERED	TBG RECOVERED	CSG RECOVERED
3/12/96	, 5 7/8" steel ₁9 ²⁵ 68 7/8" FG	94 jts 2-3/8" 5' - 95th jt	0
3/15/96	103.44' csg unaccountable		61-1/2 jts 2193.78
3/18/98	5-3/4 7/8" FG Approx. 220'		
3/19/96	18-1/3 7/8" FG Approx. 687'	22-2/3 jis 894.40' Jt avg 30.72' Total 3582.08'	
3/20/96			56 jts 1867.95'

:

Total: 4061.73' Unaccountable csg: 51.27'

Csg top should be at 4061.73' plus slack off

:

:

KMF

MALLON OIL COMPANY N. E. Lovington State C No. 1

Mar 22, 1996 RIH with 4-3/4" shoe, dressed with 3" tapering down to 2-3/6" ID, top bushing with cut fits inside, jars, DCa XO and 128 jts tbg. Rig up swivel. Trickle water down tog. Work into 5-1/2" csg top at 4113'. Ream down to where we left off yesterday at 4123'. Mill down to 4139'. Acted like we ware milling on tog. Figured we had milled off 7' of tbg. POOH. Shoe was worn on bottom, but not on ID or top bushing. RIH with same assembly. Work back into top of 5-1/2" csg and teg at 4139'. Mill down to something inside. Bottom was wore out. No marks on top bushing. SIFN.

Daily Cost: \$4835.00

Cum: \$36,718.00

- Mar 23 -24,1996 Shut Down.
- Mar 25-27,1996 Shut down for well evaluation. Stand-by Cost: \$300.00 Cum; \$37,018.00
- Mar 28, 1996 Lay down, DC8, fishing tools, TBG, 1" rods. ND BOP, NU well head, shut in well, release equipment and rig. Final report. Daity Cest; \$2938.00 Cum: \$39,958.00

No.4203 P. 9