



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

24-Jun-09

GMX RESOURCES, INC.

9400 N. BROADWAY, SUITE 600

OKLAHOMA CITY OK 73114-

LETTER OF VIOLATION - Inactive Well(s)

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that the well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

1. Immediately restore the well(s) to production, injection or disposal as applicable.
2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test
3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

IDLE WELL INSPECTION DETAIL SECTION

SUNRAY 682 LTD 003	H-36-9S-33E	30-025-22946-00-00	Inspection No. iMGB0917556567
Inspection Date:	6/24/2009 3:42:47 PM	Corrective Action Due by:	9/27/2009
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Maxey Brown	Yes	No
Comments on Inspection:	Idle Well (Rule 19.15.25.8) NO PROD REPORTED IN 139 MONTHS. NEED TO RETURN TO PROD., T/A, OR P/A WELL. ALSO NEED CURRENT OPERATOR ON SIGN (RULE 19.15.16.8). NEED TO REMOVE SURPLUS EQUIPMENT AND CONNECTIONS FROM LOCATION (RULE 19.15.10.8) THIS IS 1ST LETTER OF NON-COMPLIANCE.		
TWITTY BHF STATE 001	J-36-9S-33E	30-025-37466-00-00	Inspection No. iMGB0917555467

Inspection Date: 6/24/2009 3:24:27 PM

Corrective Action Due by: 9/27/2009

Type Inspection

Inspector

Violation?

*Significant Non-Compliance?

Routine/Periodic

Maxey Brown

Yes


No

Comments on Inspection:

Idle Well (Rule 19.15 25.8) NO PROD REPORTED IN 34 MONTHS. NEED TO RETURN TO
PROD., T/A, OR P/A WELL ALSO NEED CURRENT OPERATOR ON SIGN. (RULE
19.15 16.8) THIS IS 1ST LETTER OF NON-COMPLIANCE.

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry

Sincerely,




Hobbs OCD District Office

COMPLIANCE OFFICER

* Significant Non-Compliance events are reported directly to the U S Environmental Protection Agency, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER	017H15554612	US POSTAGE
	\$0.44	
	06/25/2009	
	Mailed From 88240	

GMX RESOURCES, INC.
9400 N. BROADWAY, SUITE 600
OKLAHOMA CITY OK 73114