Submit One Copy To Appropriate District	State of New Me	vico		Form C-103
Office Energy	y, Minerals and Natur			March 18, 2009
1625 N French Dr , Hobbs, NM)		WELL API NO. / 30-025-38449	
District II 1301 W. Grand Ave, Artesia, NM 88210 District III 1301 Proper Pd. Actes NM 87410 1220 South St. Francis Dr.			5. Indicate Type of Lea	
			STATE 6. State Oil & Gas Leas	FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 C, 14141 67	303	6. State Off & Gas Leas	e No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Vacuum Glorietta East V	_
PROPOSALS) 1. Type of Well: Gas Well Other			8. Well Number # 026Y /	
2. Name of Operator			9. OGRID Number 217817	
ConocoPhillips Company 3. Address of Operator			10. Pool name or Wildcat	
P.O. Box 51810 Midland, Tx 79710			Vacuum Glorietta	
4. Well Location Unit Letter N : 600 feet from the S line and 1558 w line				
Unit Letter feet from the line and feet from the line Section 32 Township 17S Range 35E NMPM Lea County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION PERFORM REMEDIAL WORK ☐ PLUG ANI	NIO: DABANDON □	SUB: REMEDIAL WOR	SEQUENT REPOR	TOF: ERING CASING □
TEMPORARILY ABANDON CHANGE		COMMENCE DRI		
PULL OR ALTER CASING MULTIPLE	ECOMPL 🔲	CASING/CEMENT	Т ЈОВ	
OTHER:		☑ Location is re	eady for OCD inspection	after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the				
- NO MARKER REQUIRED MUSE				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
All metal bolts and other materials have been to be removed.)	removed. Portable ba	ses have been femo	ved. (Foured offsite coller	ete bases do not nave
All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.				
/ \				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE	TITLE	Sr. Regulator	y Specialist _{DATE}	_E 7/1/2009
Dama William		Donna.J.Will	iams@	
For State Use Orby				
$\mathcal{M}_{1} \cap \mathcal{M}_{2} = \mathcal{M}_{1} \cap \mathcal{M}_{2} = \mathcal{M}_{2} \cap \mathcal{M}_{3} = \mathcal{M}_{2} \cap \mathcal{M}_{3} = \mathcal{M}_{3} \cap \mathcal{M}_{4} = \mathcal{M}_{4} \cap \mathcal{M}_{4} \cap \mathcal{M}_{4} = \mathcal{M}_{4} \cap \mathcal{M}_{4} = \mathcal{M}_{4} \cap \mathcal{M}_{4} = \mathcal{M}_{4} \cap \mathcal{M}_{4} = \mathcal{M}_{4} $				
APPROVED BY:	UI TITLE	ompliance	DAT	E 1/1/009
Conditions of Approval (it airy).		•	ω	· •