

Submit One Copy To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88201

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

March 18, 2009

RECEIVED

OIL CONSERVATION DIVISION

JUL 10 2009 220 South St. Francis Dr.

HOBBSCOCD

Santa Fe, NM 87505

WELL API NO.

30-025-12234

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-9519

7. Lease Name or Unit Agreement Name

West Dollachide Drinkard Unit

8. Well Number

35

9. OGRID Number

4323

10. Pool name or Wildcat

Dollachide Tubb Drinkard

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☐ Oil Well ☒ Gas Well ☒ Other Injection

2. Name of Operator

Chevron USA Inc

3. Address of Operator

P.O. Box 7139, Midland, Tx 79708

4. Well Location

Unit Letter N : 660 feet from the South line and 1980 feet from the West line

Section 29 Township 24S Range 38E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3217' DE

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

☒ Location is ready for OCD inspection after P&A

☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.

☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.

☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.

☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.

☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.

☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)

☒ All other environmental concerns have been addressed as per OCD rules.

☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Ronnie Hazelwood TITLE Operations Supervisor DATE 7/9/09

TYPE OR PRINT NAME Ronnie Hazelwood E-MAIL: rhazelwood@Chevron.com PHONE: 432-523-5629
For State Use Only

APPROVED BY: [Signature] TITLE Compliance Officer DATE 7/14/09

Conditions of Approval (if any):

PT OK TO RELEASE By MW ON 4/22/09

Print work order cards

Work order	DS10902074	WDDU #35 PA WELL	GANG	Target Start Date	02-19-2009	Reprint
Status	Waiting Work Order Completion					
Parent work order				WO type	SOM	
Department	DOLLARHIDE	Dollar Hide		Class		
PM schedule				Priority	4	
Cost code				Warranty		
Problem code	INSP	Inspection/Condition Monitoring		Safety		
Requested by	HGCF	GALINDO, HUMBERTO		Equipment criticality	NA	
Project				Assigned to	DHGNG1	
Standard work order				Scheduling group		
Equipment	WDDU (MCA)	FIELD; WDDU				
	DOLLARHIDE (MCA)	DOLLARHIDE OPERATIONS				
Manufacturer						
Model						
Serial number						
Date started		Date completed		Time completed		
WO description						

NEED GANG TO DIG OUT RISER ABOUT 2 FEET UNDERGROUND AND CUT OUT RISER THEN COVER BACK UP AND CLEAN AROUND LOCATION FOR TRASH AND JUNK IF ANY QUESTIONS CALL BERT 631-2749

ABOUT 3HRS
COMPLETED AS WRITTEN

Print work order cards

Activity 1				
Work order	DS10902074	Activity	1	Target Start Date 02-19-2009
Trade	GNG3	Gang (3 Person)		Duration (days) 1
Estimated hours	3			People req 3

Act Schedule				
Person responsible	Description	Maintenance equipment	Start time	Hours
DHGNG1	DOLLARHIDE GANG NO. 1 (3 MAN GANG)		02-19-2009 00:00	2

Booked hours					
Employee	Date	Time on	Time off	Total time	Tariff group

Remarks