

RECEIVED

JUL 10 2009

Submit One Copy To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBSOCD

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103

March 18, 2009

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-20326

5. Indicate Type of Lease
 STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
81583

7. Lease Name or Unit Agreement Name
New Mexico BZ State (NCT-10)

8. Well Number 4

9. OGRID Number

10. Pool name or Wildcat
Blinebry, Tubb, Drinkard

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3141' GL

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Chevron USA Inc.

3. Address of Operator
P.O. Box 7139, Midland, Tx 79708

4. Well Location
 Unit Letter m : 660 feet from the South line and 989 feet from the West line
 Section 2 Township 25S Range 37E NMPM _____ County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3141' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input checked="" type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		<input checked="" type="checkbox"/> Location is ready for OCD inspection after P&A	

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- ☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- ☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- ☒ All other environmental concerns have been addressed as per OCD rules.
- ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Ronnie Hazelwood TITLE Operations Supervisor DATE 7/9/09

TYPE OR PRINT NAME Ronnie Hazelwood E-MAIL: chazelwood@Chevron.com PHONE: 432-523-5629
 For State Use Only Ext 7602

APPROVED BY: [Signature] TITLE Compliance Officer DATE 7/14/09

Conditions of Approval (if any): PA OK TO RELEASE By MW ON 6/24/09

Print work order cards

Work order	DS11148065	NM BZ 10-4 CLEAN UP PA'd LOC.	Target Start Date	04-30-2009
Status	Waiting Work Order Completion			Reprint
Parent work order	WO type SOM		Class	
Department	DOLLARHIDE	Dollar Hide	Priority	2
PM schedule			Warranty	
Cost code	UCU802300	NEW MEXICO BZ STATE NCT-10	Safety	
Problem code	ABDN	Abandonment / Removal	Equipment criticality	
Requested by	DDOB	DOBBS, AARON (432-967-3426)	Assigned to	DHGNG1
Project			Scheduling group	
Standard work order				
Equipment	FB3812 (MCA)	WELL; NM BZ STATE NCT 10-4		
	NM-BZ-STATE-NCT-10 (MCA)	NM-BZ-STATE-NCT-10		
Location	FB3812-L (MCA)	WELL; NM BZ STATE NCT 10-4		
Manufacturer				
Model				
Serial number	30025203260000			
Date started		Date completed		Time completed
WO description				

NM BZ 10-4 BY ORDER FROM NMOCD

CLEAN PA'd WELL LOCATION.

MOVE FLOW LINE OFF THIS LOCATION COMING FROM 10-6 (THIS IS A CASING VENT LINE AND IS STILL ACTIVE) 2" POLY AND 2 7/8" STEEL.

PILE OF TRASH, JUNK AND OLD STUB POLE EAST OF DRY HOLE MARKER.

TRANFORMER BANK NORTH SIDE OF LOC. CONDUIT AND FUSE BANK(DON'Y KNOW IF WE NEED TO PULL DOWN OR NOT BUT THIS POLE AND DEAD MAN IS IN THE LOCATION THAT NEED TO BE RIPPED WHEN CLEAN UP IS COMPLETED.)

NORTH WEST EDGE OF OLD PIT AREA BIG CHUNK OF CEMENT (OLD BASE) HAUL OFF OR BURY.

FLAG NORTH WEST OF DRY HOLE MARKER IS AN OLD DEAD MAN ANCHOR THAT NEEDS TO BE REMOVED.

NEED TO RIP LOCATION AFTER CLEAN UP IS COMPLETED, ALSO CALL NMOCD WHEN ALL WORK IS COMPLETED 575-393-6161

COMPLETED AS WRITTEN