

RECEIVED

Submit One Copy To Appropriate District Office

State of New Mexico
Energy, Minerals and Natural Resources

JUL 10 2009

Form C-103

7/6/09 ~~March 18, 2009~~

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OIL API NO.

30-025-30054

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

B-9613

7. Lease Name or Unit Agreement Name

West Dollarhide Drinkard Unit

8. Well Number

94

9. OGRID Number

10. Pool name or Wildcat

Dollarhide Tubb Drinkard

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Chevron USA Inc

3. Address of Operator

P.O. Box 7139, Midland, Tx 79708

4. Well Location

Unit Letter L : 2550 feet from the South line and 130 feet from the West line

Section 32 Township 24S Range 38E NMPM Lea County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3141' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

☒ Location is ready for OCD inspection after P&A

☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.

☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.

☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.

☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.

☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.

☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)

☒ All other environmental concerns have been addressed as per OCD rules.

☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Ronnie Hazelwood TITLE Operations Supervisor DATE 7/9/09

TYPE OR PRINT NAME Ronnie Hazelwood E-MAIL: rhazelwood@Chevron.com PHONE: 432-523-5629
For State Use Only Ext 7602

APPROVED BY: [Signature] TITLE COMPLIANCE OFFICER DATE 7/14/09

Conditions of Approval (if any):

PA OK TO RELEASE

Print work order cards

Work order	DS11156568	WDDU #94 CLEANUP	BACKHOE	Target Start Date	04-30-2009	Reprint
Status	Waiting Work Order Completion					
Parent work order				WO type	CR	Class
Department	DOLLARHIDE	Dollar Hide			Priority	4
PM schedule						Warranty
Cost code	UCU881500	WEST DOLLARHIDE DRINKARD III				Safety
Problem code	INSP	Inspection/Condition Monitoring				Equipment
Requested by	JTVJ	SANCHEZ, JASON				criticality
Project						Assigned to
Standard work order						Scheduling group
Equipment	IM0876 (MCA)	WELL; WDDU 94				
	WDDU (MCA)	FIELD; WDDU				
	DOLLARHIDE (MCA)	DOLLARHIDE OPERATIONS				
Location	IM0876-L (MCA)	WELL; WDDU 94				
Manufacturer						
Model						
Serial number	30025300540000					
Date started		Date completed		Time completed		
WO description						

NEED BACKHOE TO CLEAN UP AND BACK DRAG THE LOCATION

NEED TO MAKE SURE LOCATION IS LEVEL AND NO TRASH, OLD PIPE, OR ANYTHING LEFT ON LOCATION

APP 6HRS

COMPLETED AS WRITTEN

Print work order cards

Activity 1				
Work order	DS11156568	Activity 1	Target Start Date	04-30-2009
Trade	BHOE	Backhoe and Operator	Duration (days)	1
Estimated hours	4		People req	2

Act Schedule				
Person responsible	Description	Maintenance equipment	Start time	Hours
DHBHOE1	DOLLARHIDE BACKHOE No. 1		04-30-2009 00:00	5

Booked hours					
Employee	Date	Time on	Time off	Total time	Tariff group

Remarks