



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Field Inspection Program

Preserving the Integrity of Our Environment

21-Jul-09

BURGUNDY OIL & GAS OF N M INC

401 W TEXAS STE 1003

MIDLAND TX 79701

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

STATE AA No.001

I-35-21S-34E

30-025-02605-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/21/2009	Routine/Periodic	John Harrison	Yes	No	10/24/2009	iJRH0920238796
Violations						
Absent Well Identification Signs (Rule 103)						
Surface Leaks/Spills						

Comments on Inspection: WELL SIGN LEGAL INFORMATION INCORRECT. SIGN INDICATES TOWNSHIP 34E RANGE 21S, (TRANPOSED). PUMP TANK OVERFLOW, DOCUMENTED WITH PHOTOS. LOCATION NEEDS ATTENTION.

GETTY 36 STATE COM No.001

F-36-21S-34E

30-025-26236-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/21/2009	Routine/Periodic	John Harrison	Yes	No	10/24/2009	iJRH0920237042
Violations						
Absent Well Identification Signs (Rule 103)						

Comments on Inspection: Operator name on well sign not legible. NEED TO REPLACE WELL SIGN TO COMPLY WITH RULE 19.15.3.103. 2ND letter of non-compliance. JRH

GETTY 36 STATE COM No.002

J-36-21S-34E

30-025-26541-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/21/2009	Routine/Periodic	John Harrison	Yes	No	10/24/2009	iJRH0920237420
Comments on Inspection:		Operator name on well sign not legible. NEED TO REPLACE WELL SIGN TO COMPLY WITH RULE 19.15.3.103. 2ND letter of non-compliance.				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown
above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order
summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently
plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.


Sincerely,


Hobbs OCD District Office

C.O.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

**EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240**



HASLER	017H15554612	US POSTAGE
	\$0.44	
	07/21/2009	
	Mailed From 88240	

BURGUNDY OIL & GAS OF NM INC
401 W TEXAS SYE 1003
MIDLAND, TX 79701