PNR-8/25/2009-MYB gnj. riser 2:35pm Call and left message for Bob Gilmon. Play. OK TO RELEASE.
MAB. 9/15/2009

Office	f New Mexico	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	ls and Natural Resources	March 18, 2009 WELL API NO.
District II 1301 W. Grand Ave, Artesia, NM 88216 2 4 2009L CONSER	RVATION DIVISION	30.025-05162
District III 1000 Rio Brazos Rd., Aztec, NH GBBSOCD South	th St. Francis Dr.	5. Indicate Type of Lease STATE FEE 🔀
District IV Santa	Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr , Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ((DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE		7. Lease Name or Unit Agreement Name Denton North wolfcamp
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FO PROPOSALS.)	ORM C-101) FOR SUCH	8910087370
1. Type of Well: Oil Well Gas Well X Other	Injection	8. Well Number Tr. 13 Well 6
2. Name of Operator		9. OGRID Number 01998
Stephens + Ishnson Operating Co. 3. Address of Operator		10. Pool name or Wildcat
P.O. Bx 2249, W.7. 2x 76307	<u> </u>	Denton Wolfcamp
4. Well Location Unit Letter 14: a 210 feet from the N line and feet from the line		
Section 27 Township 145 Range 37E NMPM County Lco		
11. Elevation (Show	whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDO	N 🗌 REMEDIAL WORI	
TEMPORARILY ABANDON ☐ CHANGE PLANS PULL OR ALTER CASING ☐ MULTIPLE COMPL	☐ COMMENCE DRI ☐ CASING/CEMENT	
POLE OR ALTER CASING WIDETIFLE COMPL	_	
OTHER:		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
<u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u> PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Injection line is still active to this location		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines.		
When all words has been completed return this forms to the	numerousists District office to sale	adula an insuration Please notify,
When all work has been completed, return this form to the appropriate District office to schedule an inspection. Hease notify when inspection is scheduled!		
SIGNATURE TO SERVICE	TITLE P. E.	DATE (7-19-09
The state of the s		(940)
TYPE OR PRINT NAME Bob Gilmore E-MAIL: bgilmore@sjoc.net PHONÉ: 723.2166 For State Use Only		
Malaum Sarah Alimali aliza		
APPROVED BY: Conditions of Approval (if any):	TITLE COMPLIANCE	DATE 1115 1000
Conditions of ripproval (if migg.	•	\mathcal{U}