PsAd.	OK TO RECEASE.
Submit 3 Copies To Appropriate District  State of New Mexico  Office  Niveral and Network Resources	B 9/15/2009 Form C-103 October 25, 2007
1625 N French Dr , Hobbs, NM 8724 D	WELL API NO. 30-025-37361
1301 W Grand Ave, Artesia, NM 2000 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd, Aztec, Marshall Santa Fe, NM 87505	STATE XX FEE
District IV 1220 S St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Brazos Deep State
1. Type of Well: XX Oil Well Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
Energen Resources Corporation  3. Address of Operator	162928  10. Pool name or Wildcat
3300 N."A" St., Bldg 4, Ste. 100, Midland, TX 79705	Saunders; Morrow (Gas)
4. Well Location  Unit Letter P : 660 feet from the South line and 710	fort from the Fast line
Section 34 Township 14-S Range 33-E NMPM  11. Elevation (Show whether DR, RKB, RT, GR, et	County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 2500'	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON	<del></del>
PULL OR ALTER CASING	
and the same of th	dy for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.  If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been rem	noved. (Poured onsite concrete bases do not have
to be removed.)  XX All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b	) NMAC. All fluids have been removed from
non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to sch inspection has to be made to a P&A location because it does not meet the criteria above, a	
	ory Analyst DATE 09-11-09
TYPE OR PRINT NAME E-MAIL	cherry@energen.com PHONE432-684-3692
For State Use Only Malana Collaboration of the Coll	
APPROVED BY Maley Hour TITLE Compliance Office DATE 9/15/2009  Conditions of Approval, if any:	