



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

23-Sep-09

KERNS PETROLEUM, INC.

1777 NE LOOP 410, SUITE 930

SAN ANTONIO TX 78217-

LETTER OF VIOLATION - Inactive Well(s)

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that the well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

1. Immediately restore the well(s) to production, injection or disposal as applicable.
2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.


In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

IDLE WELL INSPECTION DETAIL SECTION

JAMISON 002	E-22-24S-37E	30-025-11193-00-00	Inspection No. iMAW0926540826
Inspection Date:	9/22/2009 11:20:22 AM	Corrective Action Due by: 12/26/2009	
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Mark Whitaker	Yes	No
Comments on Inspection:	No well sign (Rule 19.115.16.8). Casing appears to be parted at surface with rods and tubing in hole. No production reported in over 16 months. NEED TO REPAIR CASING AND EITHER RETURN TO PRODUCTION, TEST FOR T/A STATUS, OR PLUG AND ABANDON WELL. ALSO NEED TO INSTALL NEW WELL SIGN. 1st notice. MW		

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.


Sincerely,


COMPLIANCE OFFICER

Hobbs OCD District Office

* Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER

017H15554612

\$0.44

09/23/2009

Mailed From 88240

US POSTAGE

KERNS PETROLEUM, INC
1777 NE LOOP 410, SUITE 930
SAN ANTONIO, TX 78217