Submit 3 Copies To Appropriate District Office	Energy Minerals and Not				Form C-103 Revised March 25, 1999	
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.			
District II OIL CONCEDIVATION DIVISION				30-025-03718		
1301 W. Grand Ave., Artesia, NM 88210  District III  1220 South St. Francis Dr.				5. Indicate Type		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV  Santa Fe, NM 87505				1	Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM				B-1705	1	
87505  SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE				7. Lease Name or Unit Agreement Name:		
"APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:				Lea 396 State		
Oil Well Gas Well Other						
2. Name of Operator Jetta Operating Co., Inc.				8. Well No.	8. Well No. 2	
3. Address of Operator				9. Pool name or Wildcat		
777 Taylor St., Suite P1-D Fort Worth, TX 76102					Dean Permo Penn	
4. Well Location						
Unit Letter F : 19	80 feet from the	West	line and	1980 feet from th	ne <u>North</u> line	
Section 35 Town	nship 15S Ra	nge 3	36E NM	PM	Lea County	
	10. Elevation (Show w	hether Di	R, RKB, RT, GR, e	etc.)		
12' KB  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
		dicate N				
NOTICE OF INTENTION TO: SUE PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				BSEQUENT RE	PORT OF: ALTERING CASING □	
		_		_	<u></u>	
TEMPORARILY ABANDON L	CHANGE PLANS		COMMENCE DI	RILLING OPNS.	PLUG AND   ABANDONMENT	
	MULTIPLE COMPLETION		CASING TEST A	AND		
OTHER:		П	OTHER: 🛛 T	EMPORARILY ABAI	NDON	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of						
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or						
recompilation.						
1 MIDILE I. II.				/ O)		
1. MIRU E-Line Unit. 2. Set CIBP @ 10290', dump 20' cement on top. 3. Performed Mechanical Integrity Test: see attached chart. 4. Pressure test to 520# held						
2. Set CIBP @ 10290', dump 20' cement on top.  3. Performed Mechanical Integrity Test: see attached chart.						
4. Pressure test to 520#, held.						
Please place well on TA status for Engineering & Geology review.						
				E058535	12023	
11 1 (6 1 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1		4 41 1	4 6 1 1 1			
I hereby certify that the information ab	ove is true and complet	e to the be	est of my knowled	ige and benef.		
SIGNATURE De la marche		TITLE	Operations	Manager	DATE <u>1/12/04</u> .	
Type or print name David Pa	tterson	Т	Telephone No.	(817) 335-1179		
(This space for State use)					JAN 1 6 2004	
APPPROVED BY Hay W - WINE TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE						
Conditions of approval, if any						
V	, 1					
This Approval of Tempora	ary lasta					
Abandonment Expires	1/16/04					

