## **New Mexico Oil Conservation Division, District I** 1625 N. French Drive DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGES TO BUREAU OF LAND MA FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 NOV 2 4 2009 Lease Serial No. HOBBS SUNDRY NOTICES AND REPORTS ON WELLS NM-69175 Do not use this form for proposals to drill or to re-enter an If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. 2. Name of Operator Primero Operating, Inc. Apache Springs Fed. #1 API Well No. 3a Address 3b. Phone No. (include area code) 30-005-21152 PO Box 1433, Roswell, NM 88202-1433 575 622 1001 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Wilden Apache Springs 11. County or Parish, State 1442' FNL & 2174' FWL, Sec. 34, T10S, R30E Chaves, New Mexico 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Subsequent Report Recomplete Other Change Plans ✓ Temporarily Abandon Plug and Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) This well has not produced since July 2008 and has been flagged by the NMOCD as Inactive. The reason for the inactivity is that the gas plant which was gathering the gas encountered mechanical problems and had to shut down. The plant is currently trying to get back up and running but the economics are tough. Well Bore Configuration: PBTD 5 1/2" CIBP @ 8115' Perforations 7590-7610' 1 SPF SEE ATTACHED FOR Packer @ 7501' on 2 7/8" tubing. **CONDITIONS OF APPROVAL** Primero Operating Plans to Temporarily abandon the well as follows: A kill truck will be used to pressure backside (between 2 7/8" tubing and 5 1/2" casing) with 500 psi. A chart recorder will be used to demonstrate packer and casing integrity. After the tubing and casing will be closed until a market for the gas is re-established. 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Phelps White Title President Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE NOV 17 2009 TRETROLEUM ENGINEE Bate Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease ROSWELL FIELD OFFICE Office which would entitle the applicant to conduct operations thereon.

APPROVED FOR 3 MONTH PERIOD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

FEB 17 2010

(Instructions on page 2)

## BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, during office hours call (575) 420-2832 or after office hours call (575) 627-0205

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for a 12 month period provided by the operator.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)