P/A'd OK TO RELEARECEIVED WUR 12/2/2009	
in the second	
HOBBSOCD	
Submit 2 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources	Form C-103 October 25, 2007
1625 N: Frénch Dr., Hobbs, NM 88240	WELL API NO. 30-025-34806
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Ékônôia Dr.	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505	STATE X FEE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Dinero State
PROPOSALS.) I. Type of Well: Oil Well X Gas Well Other	8. Well Number 1
2. Name of Operator Chesapeake Operating, Inc.	9. OGRID Nümber 147179
3. Address of Operator P.O. Box 18496	10. Pool name or Wildcat
Oklahoma Čity, Ok 73154-0496 4. Well Location	Vacuum; Upper Penn, NW (Gas)
Unit Letter_C: 660' feet from the North line and 1980' feet from the West line Section 5Township 175_Range 34É NMPMCounty Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4116' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK I PLUG AND ABANDON I. REMEDIAL WORK II PLUG AND ABANDON II. TEMPORARILY ABANDON III CHANGE PLANS COMMENCE DRILLING OPNS. III P AND A PULL OR ALTER CASING MULTIPLE COMPL	
OTHER: C Location is ready for OCD inspection after P&A	
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat höle and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
🖄 The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. 	
 All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. 	
X Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE Signa Min TITLE Senior Regulatory Co	mpl. SpDATE_11/20/2009
TYPE OR PRINT NAME Bryan Arrant E:MAIL: bryan.arrant@chk.	<u>com</u> PHONE: <u>(405)935-3782</u>
APPROVED BY: Maley Alow TITLE Compliance Office DATE 12/3/2009 Conditions of Approval (if bany)	