1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Energy Miner Oil Con 1220 Se	rals nse out	New Mex and Natura vation Div 1 St. Franc e, NM 875	l Resources vision JL is Dr.			Submit 2 Copie	Form C-141 October 10, 2003 es to appropriate e in accordance ule 116 on back side of form
Relea	se Notifica	tio			ction			_
			OPERA			🖄 Initia	l Report	Final Repor
Name of Company OXY USA Address 102 S Main Carlsbad, NM 88220			Contact Kelton Beaird Telephone No. (O) 505-887-8337 C) 575-390-1903					
Facility Name Livingston Ridge 19 fed #1				e Tank battery	0551	0) 575 5		
Surface Owner BLM	Mineral Own	)er				Lease N	[0	
	Wincial Own							
	LOCAT			TACE		API	30 025	35910
			DN OF RELEASE			Vest Line	County	23160
Construction of the second sec		N	, South Enite	330'	Eust	W	LEA	
Latit	ude		Longitud	e			WATE 25	57
	NATU	RE	OF REL	EASE			v U	
Type of Release PRODUCED WATER				Release 1240 BB			Recovered 390	
Source of Release TRANSFER PUMP			Unknown	lour of Occurrenc	e		Date and Hour of Discovery 7-12-08 @ 10:15am	
Was Immediate Notice Given?			If YES, To Whom?					
Yes No Not Required								
By Whom? Kelton Beaird Oxy HES Was a Watercourse Reached?			Date and Hour 7-12-08 11:05am   If YES, Volume Impacting the Watercourse.					
$\square$ Yes $\boxtimes$ No			If TES, volume impacting the watercourse.					
Describe Cause of Problem and Remedial Action 7 Swedge broke on the transfer pump. All fluids we Area inside the berm about 80'long by 20'wide. T location into the pasture approx. 10' long by 3'wid	ere vacuumed up he spill ran across	s the	location, pudd	led up in an area a produced water c	approx 2 out of th	20' X 10'. e pump 1	The spill also ra	n west of the
Swedge broke on the transfer pump. All fluids we Area inside the berm about 80'long by 20'wide. T location into the pasture approx. 10' long by 3'wid Describe Area Affected and Cleanup Action Taker Further delineation will be done inside the battery 2' of contamination will be excavated inside the ba be hauled to Lea Land Disposal. After excavation will be rebuilt with clean caliche. A final report w I hereby certify that the information given above is regulations all operators are required to report and/	ere vacuumed up the spill ran across le. The chloride co the c	blat a blat a bar be of the be ins t corr te to tease i	ntration of the nd field analyt low the surfac battery will b talled inside the pletion of job the best of my notifications an	produced water of ical is attached. I e the chloride con e excavated to <2. he battery and new D knowledge and u nd perform correc	Lab sam centrati 50 ppm w berms nderstar tive acti	e pump is ples will be on goes. D of chloride built with nd that purs ions for rele	50,000ppm e submitted for c bue to ongoing p s. The contamin clean native soil buant to NMOCI eases which may	onfirmation. roduction only nated soil will . The location D rules and y endanger
Swedge broke on the transfer pump. All fluids we Area inside the berm about 80'long by 20'wide. T location into the pasture approx. 10' long by 3'wid Describe Area Affected and Cleanup Action Taker Further delineation will be done inside the battery 2' of contamination will be excavated inside the bat be hauled to Lea Land Disposal. After excavation will be rebuilt with clean caliche. A final report w I hereby certify that the information given above is	ere vacuumed up the spill ran across le. The chloride co the c	blat at blat at bar be of the of the oe inst te to te to by the nedia	ntration of the nd field analyt low the surfac battery will b talled inside the pletion of job the best of my notifications are the NMOCD m the contaminati	produced water of ical is attached. I e the chloride come e excavated to <2: he battery and new battery and new knowledge and u nd perform correc arked as "Final Ro on that pose a three e the operator of n	abut of th Lab sam (centrati 50 ppm v berms nderstar tive acti eport" d cat to gr responsi	e pump ples will be on goes. D of chloride built with ad that purs ions for rela- loes not reli- ound water bility for ca	50,000ppm e submitted for c bue to ongoing p s. The contamin clean native soil muant to NMOCI eases which may eve the operator s, surface water, ompliance with	onfirmation. roduction only nated soil will . The location O rules and y endanger of liability human health
Swedge broke on the transfer pump. All fluids we Area inside the berm about 80'long by 20'wide. T location into the pasture approx. 10' long by 3'wid Describe Area Affected and Cleanup Action Taker Further delineation will be done inside the battery 2' of contamination will be excavated inside the bat be hauled to Lea Land Disposal. After excavation will be rebuilt with clean caliche. A final report w I hereby certify that the information given above is regulations all operators are required to report and/ public health or the environment. The acceptance should their operations have failed to adequately ir or the environment. In addition, NMOCD accepta	ere vacuumed up the spill ran across le. The chloride co the c	blat at blat at bar be of the of the oe inst te to te to by the nedia	ntration of the nd field analyt low the surfac battery will b talled inside the pletion of job the best of my notifications and the NMOCD m te contaminati loes not reliev	produced water of ical is attached. I e the chloride come e excavated to <2. he battery and new battery and new howledge and u nd perform correc arked as "Final Ro on that pose a three e the operator of n OIL CONS	but of th Lab sam centrati 50 ppm v berms nderstar tive acti eport" d eat to gr responsi SERV	e pump ples will be on goes. D of chloride built with nd that purs ions for rela loes not reli ound water bility for ca <u>ATION</u>	submitted for contraction of the submitted for the submitted fo	onfirmation. roduction only nated soil will . The location O rules and y endanger of liability human health
Swedge broke on the transfer pump. All fluids we Area inside the berm about 80'long by 20'wide. T location into the pasture approx. 10' long by 3'wid Describe Area Affected and Cleanup Action Taker Further delineation will be done inside the battery 2' of contamination will be excavated inside the ba be hauled to Lea Land Disposal. After excavation will be rebuilt with clean caliche. A final report w I hereby certify that the information given above is regulations all operators are required to report and/ public health or the environment. The acceptance should their operations have failed to adequately ir or the environment. In addition, NMOCD acceptant federal, state, or local laws and/or regulations.	ere vacuumed up the spill ran across le. The chloride co the c	blat at blat at bar be of the of the oe inst te to te to by the nedia	ntration of the nd field analyt low the surfac battery will b talled inside the pletion of job the best of my notifications and the NMOCD m te contaminati loes not reliev	produced water of ical is attached. I e the chloride come e excavated to <2: he battery and new battery and new knowledge and u nd perform correc arked as "Final Ro on that pose a three e the operator of n	but of th Lab sam centrati 50 ppm v berms nderstar tive acti eport" d eat to gr responsi SERV	e pump ples will be on goes. D of chloride built with nd that purs ions for rela loes not reli ound water bility for ca <u>ATION</u>	submitted for contraction of the submitted for the submitted fo	onfirmation. roduction only nated soil will . The location O rules and y endanger of liability human health
Swedge broke on the transfer pump. All fluids we Area inside the berm about 80'long by 20'wide. T location into the pasture approx. 10' long by 3'wid Describe Area Affected and Cleanup Action Taker Further delineation will be done inside the battery 2' of contamination will be excavated inside the ba be hauled to Lea Land Disposal. After excavation will be rebuilt with clean caliche. A final report w I hereby certify that the information given above is regulations all operators are required to report and/ public health or the environment. The acceptance should their operations have failed to adequately ir or the environment. In addition, NMOCD acceptan federal, state, or local laws and/or regulations.	ere vacuumed up the spill ran across le. The chloride co the c	blat at blat at bar be of the of the oe inst te to te to by the nedia	ntration of the nd field analyt low the surfac battery will b talled inside th pletion of job the best of my notifications and the NMOCD m the contaminati loes not reliev Approved by	produced water of ical is attached. I e the chloride come e excavated to <2. he battery and new battery and new howledge and u nd perform correc arked as "Final Ro on that pose a three e the operator of n OIL CONS	PONM	e pump ples will be on goes. D of chloride built with ad that purs ions for rele loes not reli ound water bility for co <u>ATION</u> ENTAL E	submitted for contraction of the submitted for the submitted fo	onfirmation. roduction only hated soil will . The location D rules and r endanger of liability human health any other
Swedge broke on the transfer pump. All fluids we Area inside the berm about 80'long by 20'wide. T location into the pasture approx. 10' long by 3'wid Describe Area Affected and Cleanup Action Taker Further delineation will be done inside the battery 2' of contamination will be excavated inside the ba be hauled to Lea Land Disposal. After excavation will be rebuilt with clean caliche. A final report w I hereby certify that the information given above is regulations all operators are required to report and/ public health or the environment. The acceptance should their operations have failed to adequately ir or the environment. In addition, NMOCD acceptan federal, state, or local laws and/or regulations. Signature:	ere vacuumed up the spill ran across le. The chloride co the c	blat a ar be of the ope instant to the ope instant	ntration of the and field analyt low the surfac battery will b italled inside the pletion of job the best of my notifications are the NMOCD me the contamination loes not reliev Approved by Approval Dat Conditions of	produced water of ical is attached. I e the chloride con e excavated to <2. he battery and nev la battery and nev knowledge and u nd perform correc arked as "Final Ro on that pose a thre e the operator of n OIL CONS District SERVIS e: 8.4.06	but of the Lab sam iccentration of the lab sam iccentratio	e pump ples will be on goes. D of chloride built with nd that purs ions for rele oes not reli ound water bility for co <u>ATION</u> <u>ENTAL</u> [ Expiration]	submitted for contraction of the	onfirmation. roduction only hated soil will . The location O rules and c endanger of liability human health any other
Swedge broke on the transfer pump. All fluids we Area inside the berm about 80'long by 20'wide. T location into the pasture approx. 10' long by 3'wid Describe Area Affected and Cleanup Action Taker Further delineation will be done inside the battery 2' of contamination will be excavated inside the ba be hauled to Lea Land Disposal. After excavation will be rebuilt with clean caliche. A final report w I hereby certify that the information given above is regulations all operators are required to report and/ public health or the environment. The acceptance should their operations have failed to adequately ir or the environment. In addition, NMOCD acceptate federal, state, or local laws and/or regulations. Signature:	ere vacuumed up the spill ran across le. The chloride co the c	blat a ar be of the ope instant to the ope instant	ntration of the and field analyt low the surfac battery will b italled inside the pletion of job the best of my notifications are the NMOCD me the contamination loes not reliev Approved by Approval Dat Conditions of	produced water of ical is attached. I e the chloride con e excavated to <2. he battery and nev la battery and nev knowledge and u nd perform correc arked as "Final Ro on that pose a three e the operator of n OIL CONS District EREVIR e: 8.4.06	but of the Lab sam iccentration of the lab sam iccentratio	e pump ples will be on goes. D of chloride built with nd that purs ions for rele oes not reli ound water bility for co <u>ATION</u> <u>ENTAL</u> [ Expiration]	50,000ppm e submitted for c bue to ongoing p s. The contamin clean native soil muant to NMOCL eases which may eve the operator s, surface water, ompliance with DIVISION ENGINEER Date: 10.6	onfirmation. roduction only hated soil will . The location O rules and c endanger of liability human health any other



.