## RECEIVED

. . . .

Submit One Copy To Appropriate District State of New Mexico Office District I  State of New Mexico Minerals and Natural Resources	Form C-103 March 18, 2009
1625 N French Dr., Hobbs, NM 88240  District II	WELL API NO./ 30-025-23598
District III 1220 South St. Francis Dr	5. Indicate Type of Lease  STATE FEE   STATE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505  Santa Fe, NM 87505	6. State Oil & Gas Lease No. LC 032326 B
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Langlie Mattix Woolworth Unit
PROPOSALS.)  1. Type of Well:   Oil Well   Gas Well   Other SW Injection	8. Well Number 003
2. Name of Operator	9. OGRID Number
Midland Operating, Inc. ✓ 3. Address of Operator	148981 / 10. Pool name or Wildcat
3100 North A, Suite E-120, Midland, Texas 79705	Langlie Mattix 7 Rivers Queen
4. Well Location 330 SEATH LESO NEXT	
Unit Letter N : 2301 feet from the North line and 1313 feet from the Pastline	
Section 33 Township 24S Range 37E NMPM County Lea  11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3239	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORLD COMMENCE DRI	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN	
OTHER:	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.  A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has	have about a Call Scale with Carl
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
• •	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE The President	DATE 3-5-2010
TYPE OR PRINT NAME Victor J. Sirgo E-MAIL: vjsirgo@sbcglobal.n  For State Use Only	et PHONE: 432-638-5551_
C. I	AC 47/11/2
APPROVED BY: TITLE Compliance Conditions of Approval (if any):	Officer DATE 03/16/2010