

PRIDE ENERGY COMPANY

(918) 524-9200 ♦ Fax (918) 524-9292

Physical Address: Kensington Tower
2250 East 73rd Street, Suite 550
Tulsa, OK 74136

Mailing Address: P.O. Box 701950
Tulsa, OK 74170-1950
Email Address: johnp@pride-energy.com

April 19, 2010

ATTN: Donna Mull
New Mexico Oil Conservation Division
1625 N. French Drive
Hobbs, NM 88240

RECEIVED

APR 22 2010

HOBBSOC

RE: South Four Lakes Unit #16

30.025.37248

Ms. Mull:

In reference to the above and your letter dated April 17, 2010, requesting additional information, please find enclosed the deviation survey and the Form C-103, subsequent report of plugging and abandoning, as requested. Regarding logs, this well was plugged and abandoned prior to reaching a depth to log. Therefore, no logs were run.

Thank you, Donna.

Sincerely,

John W. Lisle

Pride Energy Company
John W. Pride

Certified Mail, Return Receipt # 91 7108 2133 3938 1893 5828

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.