
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	RECEIVONICONSERVA	ATION DIVISION	Revised 5-27-2004	
DISTRICT I	1220 South	St. Francis Dr.	WELL API NO.	
		NM 87505	30-025-12504	\mathcal{A}
DISTRICT II 1301 W. Grand Ave, Artesia, NM 8821 DOBBSOCD		5 Indicate Type of Lease STATE X FEE	/	
DISTRICT III			6 State Oil & Gas Lease No.	-
1000 R10 Brazos Rd, Aztec,	NM 87410			
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)		North Hobbs (G/SA) Unit Section 32		
1. Type of Well:		8. Well No. 532		
Onl Well X / Gas Well Other		, , , , , , , , , , , , , , , , , , ,		
2. Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator	an Ltd.		10 Pool name or Wildcat Hobbs (G/SA)	
<u> </u>	Denver City, TX 79323			
4. Well Location				,
Unit Letter G	· 2310 Feet From The North	Feet	t From The East Line	·
Section	32 Township 18-S	Range 38-E	NMPM Lea County	,,,,,,,,,
	11. Elevation (Show whether DF, RF 3638' GL	(B, RT GR, etc.)		
Pit or Below-grade Tank	Application or Closure	-	,	
P _{1t} Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness	mil Below-Grade Tank: Volume	bbls; Construction Mat	terial	
12.	Check Appropriate Box to Indicate Na			
NOT	ICE OF INTENTION TO:	SUBS	SEQUENT REPORT OF:	
PERFORM REMEDIAL V	VORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT				
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	T JOB	
OTHER.		OTHER: Temporarily A	Abandon/TA status request	X
	Completed Operations (Clearly state all pertinent de			
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion -				
3. POOH and lay down ESP equipment. 4. RIH w/bit to 4148'. POOH w/bit. 5. RIH w/CIBP set @3875'. Dump 42' of cement on top. TOC at 3833'. ARILled out # Set Less Than 100'. 6. Test casing to 510 PSI and chart for the NMOCD. 7. ND BOP/NU TA wellhead. 8. RDPU & RU. Clean location. Well is temporarily abandoned.				
6. Test casing to 510 PSI and chart for the NMOCD.				
7. ND BOP/NU TA we	llhead.	1 -on cellon	WER GLG	
8. RDPU & RU. Clear				
RUPU 04/20/10	Inis A	opproval of Tempor	4-ZZ-2012	
RDPU 04/26/10 Abandonment Expires				
I hereby certify that the info	rmation above is true and complete to the best of my know	ledge and belief. I further certify t	that any pit or below-grade tank has been/will be	
constructed or				
closed according to NMC	OCD guidelines , a general permit	or an (attached) alternative	e OCD-approved	
SIGNATURE	rendy a Johnson	TITLE Administrative	Associate DATE 05/12/2010	
TYPE OR PRINT NAME	Mendy A Johnson E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO. 806-592-6280	
For State Use Only				
		_		
APPROVED BY	Comple	TITLE STAFF	- MGZ DATE 5-17-1	10
CONDITIONS OF APPROV	VALUE ANY:	TITLE STAGE	MGZ DATE 1 7-17-1	10



NHSAU 532-32 UniTLTRG Sec. 32, T-18-5, R-38-E API 30-025-12504

Chart Recorder
Pate Trucking Serial No. MF6-32×9
Chart 0-1000Ps; Tested 2-19-10
60 min' Run By Bud Collin's