Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103 October 25, 2005
<u>District I</u> Energy, Minerals and Natural Resources	WELL API NO.
1625 N. French Dr.,Hobbs, NM 88240	30-025-24082
1301 W. Grand Ave., Artesia, NM Grand Ave., Artesia, Arte	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd. Aztec, NM 87410 1220 South St. Francis Dr. District IV 1220 South St. Francis Dr. Santa Fe, NM 87505	STATE ☑ FEE ☐ V
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 67505 87505	A-1543-1
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUC	North Monument Grayburg San
PROPOSALS.)	Andres Unit Blk/3 8. Well Number
1. Type of Well: Oil Well 🗹 Gas Well 🗌 Other	309SW
2. Name of Operator	9. OGRID Number
Apache Corporation 3. Address of Operator	10. Pool Name
6120 S. Yale, Ste. 1500 Tulsa, OK 74136	WSW-San Andres √
4. Well Location Unit Letter I: 1650' feet from the S line and 990' feet from the E line	
Section 17 Township 19S Range 37E	NMPM County Lea
11. Elevation (Show whether DR, RKB,RT, GR, etc.)	
12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O	
PULL OR ALTER CASING	
DOWNHOLE COMMINGLE	
OTHER: Location is All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit per	ready for OCD inspection after P&A
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from the lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Pou	red onsite concrete bases do not have
to be removed.) All other environmental concrens have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All f	uids have been removed from
non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one	
inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE Such TITLE Reclamation For	reman DATE 5/12/10
TYPE OR PRINT NAME Guinn Burks E-MAIL guinn.burks@apache	ecorp.com PHONE: 432-556-9143
For State Use Only	
APPROVED BY: Valuation TITLE Compliance Of Conditions of Approval (if any):	Ficer DATE 5/24/2010