RECEIVED

Ad. OK TO RELEASE. SB 6/18/2010

JUN 0 7 ZÜÜÜ Submit One Copy To Appropriate District Office State of New Mexico HOBBSE State of the Wileland Natural Resources Form C-103 Office March 18, 2009 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-025-28438 District II OIL CONSERVATION DIVISION 1301 W Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE 🔀 FEE \square 1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S St. Francis Dr , Santa Fe, NM B-2229 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Phillips E State (#31138) DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number 34 PROPOSALS) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number ConocoPhillips Company 217817 3. Address of Operator 10. Pool name or Wildcat Sanmal' P.O. Box 51810 Midland, Tx 79710 -Wildcat Queen ; west 4. Well Location Unit Letter P: 760 feet from the S line and 720 feet from the line Section 9 / Township 175 Range 33 E NMPM 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4183 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON □ REMEDIAL WORK \Box ALTERING CASING □ COMMENCE DRILLING OPNS.□ **TEMPORARILY ABANDON** CHANGE PLANS P AND A PULL OR ALTER CASING MULTIPLE COMPL \Box CASING/CEMENT JOB □ Location is ready for OCD inspection after P&A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from nonretrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to schedule an inspection. Sr. Regulatory 6/4/2010 **SIGNATURE TITLE** DATE Donna Williams Donna.J.Williams@ TYPE OR PRINT NAME E-MAIL: PHONE: Conocophillips.com

For State Use Only Conditions of Approval (if