RECEIVED

JUN 29 2010

Submit 2 Copies To Appropriate District Office District I HOBBERGY, Minerals and Natural Resources	Form C-103
	October 25, 2007 WELL API NO.
1625 N French Dr., Hobbs, NM 88240 District II	30-025-27540
OIL CONSERVATION DIVISION 1301 W Grand Ave , Artesia, NM 88210 1200 G. A. C. F. S.	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd, Aztec, NM 87410 1220 South St. Francis Dr.	STATE FEE
District IV Santa Fe, NM 8/303	6. State Oil & Gas Lease No.
1220 S St Francis Dr , Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Lea 407 State
PROPOSALS)	8. Well Number 6
1. Type of Well: Oil Well Gas Well Other	
2. Name of Operator Devon Energy Production Co. L.P.	9. OGRID Number 6137
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 250, Artesia, NM 88210	San Simon Yates; North (Association)
4. Well Location	
Unit Letter C: 660 feet from the North line and 1980 feet from the West line	
Section 33 Township 21S Range 35E NMPM County Lea	√
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3636 KB 3625 GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRII	
PULL OR ALTER-CASING MULTIPLE COMPL CASING/CEMENT JOB	
* Inspection #iMAW1013144303: Devon believes this OTHER	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION	N HAS BEEN WELDED OR
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	ved. (Poured onsite concrete bases do not have
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from	
non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one	
inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
$ \qquad \qquad$	
SIGNATURE TITLE Field Tech DATE 6/25/10	
TYPE OR PRINT NAME Denise Menoud E-MAIL: denise.menoud@dvn.com PHONE: 575-748-3371	
For State Use Only	
Approved the state of the state	
Conditions of Approval (if any): TITLE Compliance Officer DATE 07/01/2010	
Conditions of Approval (II ally).	
A STATE OF THE STA	- N- (