

State of New Mexico
Energy, Minerals and Natural Resources

RECEIVED
AUG 16 2010
HOBBSOCD

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-39105 /
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-5883
7. Lease Name or Unit Agreement Name Mandrell BMT State Com ✓
8. Well Number 2 /
9. OGRID Number 025575 ✓
10. Pool name or Wildcat Wildcat; Mississippian (Gas)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐ P&A

2. Name of Operator
Yates Petroleum Corporation ✓

3. Address of Operator
105 South Fourth Street, Artesia NM 88210

4. Well Location

Unit Letter: K : 1650 feet from the South line and 1980 feet from the West line
Section 18 Township 14S Range 35E NMPM Lea County ✓

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4061' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/4/10 – 7 yards of gravel were put in the hole followed by 8 bags of Sackrete. A plate with the well information was placed on top of the cement. The hole was then filled with dirt to surface (3'). Area was recontoured. **WELL IS PLUGGED AND ABANDONED.**

CONDITIONS OF PA APPROVAL: Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection".

Spud Date:

8/26/08

Rig Release Date:

4/24/09

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tina Huerta TITLE Regulatory Compliance Supervisor DATE August 13, 2010

Type or print name Tina Huerta E-mail address: tinah@yatespetroleum.com PHONE: (575) 748-1471

For State Use Only

APPROVED BY: [Signature] TITLE STAFF MGR DATE 8-16-10
Conditions of Approval (if any): RM