RECEIVED

P/A'd. OK TO RELEASE.

Submit One Copy To Appropriate District Office Form C-103 State of New Mexico HOBBS Chergy, Minerals and Natural Resources March 18, 2009 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-025-20320 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE X FEE 1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S St Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH North Vacuum Abo Unit 8. Well Number 98 -1. Type of Well: Oil Well Gas Well X Other-Injection 9. OGRID Number 2. Name of Operator 005380 XTO Energy, Inc. 10. Pool name or Wildcat 3. Address of Operator Vacuum; Abo, North 200 N. Loraine, Ste. # 800, Midland, Texas 79701 4. Well Location Unit Letter J: 1980' feet from the South line and 1780' feet from the East line Section 26 Township 17 S Range 34 E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING ☐ REMEDIAL WORK PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON П P AND A TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS.□ MULTIPLE COMPL \Box CASING/CEMENT JOB PULL OR ALTER CASING □ Location is ready for OCD inspection after P&A OTHER: N/A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. N/A Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. (top soil added to promote vegetative growth)
- X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- N/A If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- X All other environmental concerns have been addressed as per OCD rules. (seeded with BLM Mix # 2)
- X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Jone Judo TITLE: Maintenance Foreman DATE: 08/18/2010

TYPE OR PRINT NAME: Gene Hudson E-MAIL: richard_hudson@xtoenergy.com PHONE: 575-441-1634

For State Use Only

PPROVED BY: Majer Stown TITLE Compliance Officers on ditions of Approval (if any):

DATE 8/24/2010

X. 2.