

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88340  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87401  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
**RECEIVED**  
OIL CONSERVATION DIVISION  
OCT 05 2010  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
**HOBBSOCD**

Form C-103  
May 27, 2004

WELL API NO. 30-025-05309	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Denton SJ	
8. Well Number 1	
9. OGRID Number 151416	
10. Pool name or Wildcat SWD; Wolfcamp-Penn-Miss-Devonain	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other - SWD	
2. Name of Operator Fasken Oil and Ranch, Ltd.	
3. Address of Operator 303 W. Wall, Suite 1800, Midland, TX 79701	
4. Well Location Unit Letter <u>D</u> : <u>660'</u> feet from the <u>North</u> line and <u>660'</u> feet from the <u>West</u> line Section <u>13</u> Township <u>15S</u> Range <u>37E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3780' DF	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>	
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____	
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Response to violation letter ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Fasken Oil and Ranch, Ltd. is in receipt of your letter of violation on the S.J. Denton No. 1. This well was plugged and abandoned on June 9, 2007. The site reclamation has been completed as far as the P&A of this wellbore is concerned. The overall pad site cannot be reclaimed at this time as this pad site is the battery site and pump station location for Fasken's Denton SWD System. The location includes some 14 tanks (water storage, gun barrels, skim oil tanks) and a pump station. The entire pad area is bermed and is necessary for operations of the Denton SWD System. The Denton SWD System will be active for many years as a disposal system for the Denton Field. The surface owner, Mr. Darr Angell, is fully aware of our operations and the fact that the No. 1 well has been plugged. Fasken hereby requests this letter of violation be revoked.

**DENIED**

575-393-6161 x102

P/A FINAL Required  
for Release. Called Kim T.  
Angell

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Kim Tyson TITLE Regulatory Analyst DATE 10-1-2010

Type or print name Kim Tyson  
**For State Use Only**

E-mail address: kimt@forl.com

Telephone No. (432) 687-1777

APPROVED BY: [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of Approval (if any): \_\_\_\_\_

**DENIED**