Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> Energy, Minerals and Natural Resources			June 19, 2008 WELL API NO.
1625 N French Dr , Hobbs, NM 88240 District II 1301 W. Grand Ave , Artesia, NM 88210 The property of the Conservation Division			3004110472
1301 W. Grand Ave, Artesia, NM 88210 1220 South St. Francis Dr.			5. Indicate Type of Lease
District III 1000 Rio Brazos Rd, Aztec, NM (13 2010) 1220 South St. Francis Dr. Santa Fe, NM 87505			STATE S FEE
District IV 1220 S St. Francis Dr., Santa Februs BSOCD 87505			6. State Oil & Gas Lease No. OG1395
87505			
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAI	ES AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLU	JG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Todd Lower SA Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other:			8. Well Number 358
2. Name of Operator	/		9. OGRID Number 16696
Oxy USA Inc.			10. D. I. W''I.
3. Address of Operator 1502 W. Commerce, Carlsbad, NM 83	งวาก		10. Pool name or Wildcat Todd Lower San Andres
	3220		Todd Lower Sun Andres
4. Well Location Unit Letter_H_:1980_feet from the North_ line and660feet from the _Eastline			
Section 35 Township 7S Range 35E NMPM County Roosevelt			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
4180'			
12. Check Ap	propriate Box to Indicate N	ature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	PLUG AND ABANDON	REMEDIAL WOR	
TEMPORARILY ABANDON			
_	MULTIPLE COMPL	CASING/CEMEN	IT JOB
DOWNHOLE COMMINGLE			
OTHER: Reclaim Location		OTHER:	Reclaim Location
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
All Hard Pan was removed on all locations and roads. These areas were then tested for TPH, BTEX, and Chlorides. Once verified that all			
levels were below acceptable limits, these areas were reclaimed by burying any soil not native for topsoil, ripped, and re-seeded with			
seeding native to this area. Flat plate was installed for the dry-hole marker.			
	•		
,			
Spud Date:	Rig Release Da	ite:	
	i	<u> </u>	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE DATE			
Type or print name Kelton Beaird E-mail address: PHONE: 575-628-4121_			
Type or print name Kelton Beaird E-mail address: PHONE: 575-628-4121			
50 / Sont 10 10 10 10			
APPROVED BY: TITLE THAT MET DATE 10-18-18			