Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I			June 19, 2008	
1625 N French Dr., Hobbs, NM 88240			WELL API NO./ 3004110167	
District II 1301 W. Grand Ave, Artesia, NM SET CEIVOE CONSERVATION DIVISION		5. Indicate Type of Lea	nse	
District III 1000 R10 Brazos Rd., Aztec, NM 87007 13 2010 1220 South St. Francis Dr. Santa Fe, NM 87505		STATE 🛛	FEE	
1220 C St. Francis Dr. Conta Ea NM		6. State Oil & Gas Lea	se No.	
1220 S St Francis Dr , Santa Fe, NM 87505 HOBBSUCD				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Todd Lower SA Unit	
PROPOSALS )   1. Type of Well: Oil Well			8. Well Number 366	
2. Name of Operator 7			9. OGRID Number	<b>W</b>
Oxy USA Inc.			16696 /	
3. Address of Operator			10. Pool name or Wildcat	
1502 W. Commerce, Carlsbad, NM 88220			Todd Lower San Andres	
4. Well Location				
Unit Letter_F_:1980_feet from the North_ line and1980feet from the _Westline				
Section 36 Township 7S Range 35E NMPM County Roosevelt  11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
4171'				
			Section and Committee and Comm	
12. Check A	ppropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASII				
TEMPORARILY ABANDON				
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMENT JOB				
DOWNHOLE COMMINGLE				
OTHER: Reclaim Location	on	·	Reclaim Location	
13 Describe proposed or comple	eted operations (Clearly state all 1	ertinant datails, and	d give pertinent detection	luding agtimated data
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
All Hard Pan was removed on all locations and roads. These areas were then tested for TPH, BTEX, and Chlorides. Once verified that all				
levels were below acceptable limits, these areas were reclaimed by burying any soil not native for topsoil, ripped, and re-seeded with				
seeding native to this area. Flat plate was installed for the dry-hole marker.				
Accomtad 6- m				
Accepted for Record Only				
		<del></del>		
Spud Date:	Rig Release Da	ite:	į	
	1 / /			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE				
Type or print nameKelton Beaird For State Use Only	E-mail address:		PHONE:575-6	528-4121
APPROVED BY: Jonesha TITLE STAFF MEZ DATE 10-18-10				
	,		Pr .	