

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88211  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

RECEIVED  
NOV 09 2010  
HOBBSOCD

CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-22797
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other DISPOSAL <input checked="" type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator RICE OPERATING COMPANY.		6. State Oil & Gas Lease No.
3. Address of Operator 112 WEST TAYLOR, HOBBS NM 88240		7. Lease Name or Unit Agreement Name BLINEBRY-DRINKARD
4. Well Location Unit Letter <u>H</u> : 1872 feet from the <u>NORTH</u> line, and <u>233</u> feet from the <u>EAST</u> line Section <u>35</u> Township <u>22S</u> Range <u>37E</u> NMPM County <u>LEA</u>		8. Well Number <u>H-35</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3293' GL		9. OGRID Number
		10. Pool name or Wildcat SAN ANDRES SWD

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: MIT ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

THIS WELL FAILED A MIT TEST ON OCTOBER 27, 2010. THE CIRCUMSTANCES OF THAT TEST WERE REVIEWED, AND IT WAS DETERMINED THAT FURTHER TESTING WAS WARRANTED. ALL CONNECTIONS TO THE WELL WERE REMOVED, AND A LEAK WAS REPAIRED ON THE SOUTH SIDE OF THE WELL HEAD. THE WELL WAS THEN RE-TESTED WITH A PUMP TRUCK TO 420 PSI, AND PASSED A 30 MINUTE TEST. THE HOBBS OCD OFFICE WAS THEN NOTIFIED, AND A OCD FIELD REPRESENTATIVE CAME TO THE LOCATION TO WITNESS A NEW TEST. AS WITNESSED, THIS WELL PASSED A 30 MINUTE MIT PER OCD REGULATIONS.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Marvin Burrows*

TITLE : ENGINEERING MANAGER DATE 11/09/2010

Type or print name MARVIN BURROWS E-mail address: mburrows@riceswd.com PHONE: 575-393-9174

For State Use Only


APPROVED BY:

*[Signature]*

TITLE STAFF MGR

DATE 11-15-10

Conditions of Approval (if any):



GRAPHIC CONTROLS CORPORATION  
BUFFALO, NEW YORK

*W. J. Brown*

*Rec  
Opns.  
B-D. It  
#35*

*4/8/2010*

BR 2221

*Presented by  
W. J. Brown  
Oct 17, 2010  
of 100*

*300*

Pucc  
H 35

Pat Fuller  
Machaskey Oilfield  
Track # 13