AMTEX ENERGY, INC.

LEA ED STATE NCT-A 001

API# 30-025-02387

S-16 T-19S R-34E LEA COUNTY

NOVEMBER 5TH 2010

RECEIVED NOV 0 9 2010 HOBBSOCD

CLOSURE REPORT

For this site the producers excavated a 20'x 15'x2.5' pit to be used as a temporary work over pit for this site, the pit was unlined and was north of pumping unit well head in pasture. Nothing was ever produced into pit so samples were taken at a depth of 2.5' field analytical data showed area to be clean so samples were taken to Cardinal labs and had a full analysis done. Results came back clean from lab and analytical data was taken to Geoffry Lecking at OCD, after looking at results was given written permission to go ahead and backfill pit.

Crew brought in 18yds of blow sand to begin filling in pit, used surrounding sand to push and fill in rest of excavation. Crew then used rest of sand in area to put land back to its natural contour. Reseeding will be done according to OCD standards or whatever landowner wants to use.

If you have any questions or comments please give me a call at 575-631-8037

Jacob Melancon

Environmental Supervisor





<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 BBSOCD 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Alternative Method:

State of New Mexico NOV 09 2010 State of New Mexico
Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr.

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office. For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application

Santa Fe, NM 87505

Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method
Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.
Operator: Amtex Energy, Inc., OGRID#: O00785 Address: P. O. Box 3418; Midland, TX 79702 - 3418 Facility or well name: LEA ED State NCT-A OO1 API Number: 30-025-02387 OCD Permit Number: P1-02613 U/L or Qtr/Qtr SW40fSW (ection 16 Township 198 Range 34E County: Lea Center of Proposed Design: Latitude Longitude NAD: 1927 1983
Surface Owner: Federal State Tribal Trust or Indian Allotment
Z Pit: Subsection F or G of 19.15.17.11 NMAC Temporary: Drilling Workover Drilling Workover Permanent Emergency Cavitation P&A Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other String-Reinforced Liner Seams: Welded Factory Other Volume: Wolded bbl Dimensions: L37 x W 6 x D 265
3.
3. Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent)
3. Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other
Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other
3. Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other
Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other
Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other Liner Seams: Welded Factory Other
Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other Liner Seams: Welded Factory Other Seams: Subsection I of 19.15.17.11 NMAC
Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other Liner Seams: Welded Factory Other Subsection I of 19.15.17.11 NMAC Below-grade tank: Subsection I of 19.15.17.11 NMAC
Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other Liner Seams: Welded Factory Other Other Tank Construction material: Secondary containment with leak detection Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off Visible sidewalls and liner Visible sidewalls only Other
Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation:

Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

6. Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) □ Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church) □ Four foot height, four strands of barbed wire evenly spaced between one and four feet □ Alternate. Please specify	hospital,				
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other Monthly inspections (If netting or screening is not physically feasible)					
8. Signs: Subsection C of 19.15.17.11 NMAC 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers Signed in compliance with 19.15.3.103 NMAC					
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	office for				
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying pads or above-grade tanks associated with a closed-loop system.					
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No				
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No				
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	Yes No				
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No ☐ NA				
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application.					
 NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. Written confirmation or verification from the municipality; Written approval obtained from the municipality 					
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No				
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No				
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No				
Within a 100-year floodplain FEMA map	Yes No				

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API Number:
Previously Approved Operating and Maintenance Plan API Number: (Applies only to closed-loop system that use
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
13.
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative
Proposed Closure Method: Waste Excavation and Removal
☐ Waste Removal (Closed-loop systems only)
On-site Closure Method (Only for temporary pits and closed-loop systems)
☐ In-place Burial ☐ On-site Trench Burial ☐ Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
15.
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

16. <u>Waste Removal Closure For Closed-loop Systems That Utilize Above Ground</u> <i>Instructions: Please indentify the facility or facilities for the disposal of liquids,</i>						
facilities are required.						
Disposal Facility Name:	Disposal Facility Permit Number:	*				
Disposal Facility Name:						
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used for future service and operations? Yes (If yes, please provide the information below) No						
Required for impacted areas which will not be used for future service and operations: Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC						
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.						
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Dat	a obtained from nearby wells	☐ Yes ☐ No ☐ NA				
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Dat	a obtained from nearby wells	☐ Yes ☐ No ☐ NA				
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells						
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other siglake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	gnificant watercourse or lakebed, sinkhole, or playa	Yes No				
Within 300 feet from a permanent residence, school, hospital, institution, or church - Visual inspection (certification) of the proposed site; Aerial photo; Satellit		☐ Yes ☐ No				
 Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site 						
Within incorporated municipal boundaries or within a defined municipal fresh wat adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approx		Yes No				
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site						
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining	g and Mineral Division	☐ Yes ☐ No				
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geolog Society; Topographic map	y & Mineral Resources; USGS; NM Geological	☐ Yes ☐ No				
Within a 100-year floodplain FEMA map		☐ Yes ☐ No				
18. On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Construction/Design Plan of Temporary Pit (for in-place burial of a drying protocols and Procedures - based upon the appropriate requirements of 19.1 Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Disposal Facility Name and Permit Number (for liquids, drilling fluids and Soil Cover Design - based upon the appropriate requirements of Subsection Re-vegetation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection	quirements of 19.15.17.10 NMAC f Subsection F of 19.15.17.13 NMAC ppropriate requirements of 19.15.17.11 NMAC pad) - based upon the appropriate requirements of 19.15.17.13 NMAC quirements of Subsection F of 19.15.17.13 NMAC Subsection F of 19.15.17.13 NMAC drill cuttings or in case on-site closure standards cannot H of 19.15.17.13 NMAC I of 19.15.17.13 NMAC	15.17.11 NMAC				

19. Operator Application Certification:	
I hereby certify that the information submitted with this application is true, ac	curate and complete to the best of my knowledge and belief.
Name (Print):	Title:
Signature:	Date:
e-mail address:	Telephone:
20	
OCD Approval: Permit Application (including closure plan) Closur	CSK1 11- C-6110A
	Approval Date: 1102110
Title: Environmental Engineer	OCD Permit Number: P1-02613
Closure Report (required within 60 days of closure completion): Subsect Instructions: Operators are required to obtain an approved closure plan prowing The closure report is required to be submitted to the division within 60 days section of the form until an approved closure plan has been obtained and the	ior to implementing any closure activities and submitting the closure report. of the completion of the closure activities. Please do not complete this
	M closure compensation 1-7
22. Closure Method: Waste Excavation and Removal □ On-Site Closure Method □ Alt If different from approved plan, please explain. ☒ PIT NEVER US	ernative Closure Method Waste Removal (Closed-loop systems only)
Closure Report Regarding Waste Removal Closure For Closed-loop Syst Instructions: Please indentify the facility or facilities for where the liquids, two facilities were utilized. Disposal Facility Name:	drilling fluids and drill cuttings were disposed. Use attachment if more than Disposal Facility Permit Number:
Disposal Facility Name:	Disposal Facility Permit Number:
Were the closed-loop system operations and associated activities performed o Yes (If yes, please demonstrate compliance to the items below) No	
Required for impacted areas which will not be used for future service and open Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique	erations:
24. <u>Closure Report Attachment Checklist: Instructions: Each of the following</u>	ng items must be attached to the closure report. Please indicate, by a check
mark in the box, that the documents are attached. □ Proof of Closure Notice (surface owner and division) □ Proof of Deed Notice (required for on-site closure) □ Plot Plan (for on-site closures and temporary pits) □ Confirmation Sampling Analytical Results (if applicable) □ Waste Material Sampling Analytical Results (required for on-site closu□ Disposal Facility Name and Permit Number □ Soil Backfilling and Cover Installation □ Re-vegetation Application Rates and Seeding Technique □ Site Reclamation (Photo Documentation)	
25. Operator Closure Certification:	
I hereby certify that the information and attachments submitted with this closure left. I also certify that the closure complies with all applicable closure required.	ure report is true, accurate and complete to the best of my knowledge and irements and conditions specified in the approved closure plan.
Name (Print): William J. Savage	Title: President
Signature: William J. Davage	Date: 11/05/10
e-mail address: bill savage a VPV 70h. NPJ	Telephone: 432-686-0847



PHONE (575) 393-2325 ° 101 E. MARLAND " HUBBS, NM 86240

September 29, 2010

JACOB MELANCON

3 K OIL & GAS

101 E. PANTHER

JAL, NM 88252

RE: LEA ED STATE BATTERY #1

Enclosed are the results of analyses for samples received by the laboratory on 09/22/10 15:30.

Cardinal Laboratorles is accredited through Texas NELAP for:

Method SW-846 8021

Benzene, Toluene, Ethyl Benzene, and Total Xylenes

Method SW-846 8260

Benzene, Toluene, Ethyl Benzene, and Total Xylenes

Method TX 1005

Total Petrolcum Hydorcarbons

Certificate number T104704398-08-TX. Accreditation applies to solid and chemical materials and non-potable water matrices.

Cardinal Laboratories is accreditated through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2

Haloacetic Acids (HAA-5)

Method EPA 524.2

Total Trihalomethanes (TTHM)

Method EPA 524.4

Regulated VOCs (V2, V3)

Accreditation applies to public drinking water matrices.

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Celey D. Keene

Lab Director/Quality Manager

Celeg D. Keine

approved by theiften Shing Enjures MMOCD-Holls

10/12/10

Page 1 of 5



PHONE (575) 393-2326 * 101 S. MARLAND * HOBBS, NM 88240

Analytical Results For:

3 K OIL & GAS
JACOB MELANCON
101 E. PANTHER
JAL NM, 88252
Fax To: 395-2164

Received:

09/22/2010

Reported:

09/29/2010

Project Name:

LEA ED STATE BATTERY #1

Project Number:

#136

Project Location:

STATE BATTERY #1

Sampling Date:

sampling bace.

09/22/2010

Sampling Type:

Soil

Sampling Condition:

Cool & Intact

Sample Received By:

Jodi Henson

Sample ID: S1 2-3' (H020899-01)

STEX 8021B	mg/	kg	Analyze	d By: cms		.,			
Analyte	Result	Reporting Limit	Analyzed	Method Blank	85	% Recovery	True Value QC	RPD	Qualifiér
Benzene*	<0.025	0.025	09/24/2010	ND	1.89	94.4	2.00	4.90	
Toluene*	<0.025	0.025	09/24/2010	ND	2.20	110	2,00	6.46	
Ethylbenzene*	<0.025	0.025	09/24/2010	ND	2.26	113	2.00	8.22	
Total Xylenes*	<0.075	0.075	09/24/2010	ND	6.76	113	6.00	8.01	
Surrogate: 4-Bromofluorobenzene (PIL	104 9	6 80-120							
Chloride, SM4500Cl-B	mg/kģ		Analyzed By: HM						
Analyte	Result	Reporting Limit	Analyzed	Mcthod Blank	BS	% Recovery	True Value QC	RPD	Qualifler
Chloride	<16.0	16.0	09/24/2010	ND	432	108	400	3.77	
TPH 8015M	mg/	kg	Analyze	d By: AB					
Analyto	Result	Reporting Umit	Analyzed	Method Blank	829	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<5,0.0	10.0	09/26/2010	ND	173	86.5	200	1.68	
DRO >C10-C28	106	10.0	09/26/2010	ND	152	75.9	200	4.78	
Surrogate: 1-Chlorooctane	95.75	% 70-130						••••	
Surrogate: 1-Chlorooctadecane	96.45	% 70-130							

Cardinal Laboratories

*=Accredited Analyte

FLEASE NOTE: Listenty and contenges. Cardinals lightly and dishes exclusive remedy for any claim integra, whether taked in contenct or teru shall be limited to the amount part to them, including them for replication and the content of the applicable service. In on ment, that Cardinal be listed for including or consequential changes, including, whether, limited me, whether, limited ment, including the content of the applicable service. In on ment, that Cardinal be listed for including or consequential changes, including, whether, limited ment, including the content including them. It is a possible to the periodical to the periodical of the services because of the content of the applicable of the above sometime for the above sometime for the content of the content of the above sometime for the above sometime for the content of the content of the above sometime for the content of the content of the above sometime for the content of the content of the above sometime for the content of the content of

Celey D. Keene



PHONE (575) 393-7326 * 101 E, MARLAND * HORRS, NM 88240

Analytical Results For:

3 K OIL & GAS JACOB MELANCON 101 E. PANTHER JAL NM, 88252 Fax To: 395-2164

Received:

09/22/2010

Reported:

09/29/2010

Project Name:

LEA ED STATE BATTERY #1

Project Number:

#136

Project Location:

STATE BATTERY #1

Sampling Date:

09/22/2010

Sampling Type:

Soff

Sampling Condition:

Cool & Intact

Sample Received By:

Jodi Henson

Sample ID: \$2 2-3' (H020899-02)

BTEX 8021B	mp/	kg	Analyze	d By: cms				,	
Analyte	Result	Reporting Limit	Analyzed	Method Blank	В\$	% Recovery	True Válue QC	RPD	Qualifier
Benzene*	<0.050	0.050	09/24/2010	ND	1.89	94.4	2.00	4.90	
Toluene*	0.120	0.050	09/24/2010	ND	2,20	110	2.00	6.46	
Ethylbenzeno*	0.064	0.050	09/24/2010	ND	2.26	113	2.00	8.22	•
Total Xylenes*	0.200	0.150	09/24/2010	ND	6.76	113	6.00	8.01	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Surrogate: 4-Bromofluorobenzene (PIL	95.5	% 80-120)						
Chloride, SM4500Cl-B	mg/	kg	Analyze	d By: HM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	65	% Recovery	True Value QC	RPD	Qualifier
Chloride	16.0	16.0	09/24/2010	ND	432	108	400	3.77	
TPH 8015M	mg/	kg	Analyze	d By: AB					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	8 \$	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	09/26/2010	ND	173	86.6	200	1.68	
DRO >C10-C28	<10.0	10.0	09/26/2010	ND	152	75.9	200	4.78	
Surrogate: J-Chlorooctane	93.3	26 70-130		•••••••					
Surrogate: 1-Chloroociadecane	96.3	% 70-130)						

Cardinal Laboratories

*=Accredited Analyte

SUPPICE NOTE: Linkship and Dannages. Candesina Makilay and dieta's endasive remody for any dairn arising, whether based in contract or tank, shall be limited to the normal read by client for employers. All claims, including those for negligence and any other clause subspaces and he deemed washed washed



PHONE (575) 303-2326 * 101 E. MARLAND * HORRS, NM 90240

Notes and Definitions

The spike recovery was outside acceptance limits for the MS and/or MSD due to matrix interference. The LCS and/or LCSD wore within acceptance limits showing that the laboratory is in control and the data is acceptable.

ND Analyte NOT DETECTED at or above the reporting limit

RPD Relative Percent Difference

** Samples not received at proper temperature of 6°C or below.

Insufficient time to reach temperature.

Chloride by SM4500CF8 does not require samples be received at or below 6°C

Samples reported on an as received basis (wet) unless otherwise noted on report

Cardinal Laboratories

*=Accredited Analyte

PI FACE NOTE: Literally and Delining to Continuely individually and climits environs memory for may date entirely, whether bread in contract or text, shall be inhered to the equation of the population of the population of the environment of the population of the p

Celey & Keine



ARDINAL LABORATORIES 101 East Marland, Hobbs, NM 88240

(575) 393-2326 FAX (575) 393-2476

company Name: 3K Oil and 645		BILL 10	ANALYSIS REQUEST
roject Manager: Took Malancon		P.O.#: 34/8	
Address: 101 E. Pourther		Company: Amter Energy	
City: Jal State: N.M. Zip:	ip: 88252	Attn:	
Phone #: 575-375- 2654 Fax #: 5255-375	395- 2/62	Address:	
#136	ļ	City: Mid and	
Ce	ru #/	State: TX Zip: 79702 - 3418	
Project Location: State Battery # 1	(Phone #:	
Sampler Name: Jacob Mulancon		Fax #:	
FOR LAB USE ONLY	MATRIX	PRESERV. SAMPLING	
Lab I.D. Sample I.D.	(G)RAB OR (C)OMP. # CONTAINERS GROUNDWATER WASTEWATER SOIL OIL SLUDGE	OTHER: ACID/BASE: ICE / COOL OTHER: DATE	
HZD899.1 51 2-3'	? _ X	9.22 12:15	
2 52 2.3'	х ×	9.22 12:25	
PLEASE NOTE: Justice you consume to the state of the stat	lain ansing whether based in contract of	r torr, shall be limited to the amount paid by the client for the sep- sceived by Cardinal within 30 days after completion of the app	ticaple

Time:

Terminal of Data Control of Data Control of Consequental Consequental damages, including without initiation, business interruptions loss of use, or loss of godits insured by stent, its subsidiaries.

Thomas of accessors along out of or related to the performance of services hereunder by Chamal regardless of whether such daim is based upon any of the above stated reasons or otherwise.

Phone Result:

Fax Result:


Fax Result:

REMARKS: Relinquished By ampler - UPS - Bus - Other: FORM-008 Jered By: (Circle One) Received By CHECKED BY: Smail Results to: Ja cub @ 3t oil and gas. com ☐ Yes ☐ No Add'l Phone #:
☐ Yes ☐ No Add'l Fax #:

† Cardinal cannot accept verbal changes. Please fax written changes to 575-393-2476

Revision 1.0

Amtex Energy
Lea ED State Battery #1
SW 1/4 of SW 1/4
S-16 T-195 1 34E
Lea Country
September 22 2010



Sample ID	Depth	Time	Reding	• j
SI	2-3'	12:15	5 x20	= 100
<i>5</i> 2_	2'-3'	12:25	5 x 20	= 100