



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Jim Noel

Cabinet Secretary

Karen W. Garcia

Deputy Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Field Inspection Program

"Preserving the Integrity of Our Environment"

22-Dec-10

MELROSE OPERATING COMPANY

ONE CHASEWOOD - SUITE 310 20333 CHASEWOOD PARK

HOUSTON TX 77070

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

CONE JALMAT YATES POOL UNIT No.336

H-24-22S-35E

30-025-33044-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
12/22/2010	Routine/Periodic	Mark Whitaker	Yes	No	1/31/2011	iMAW1035644373
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection: Equipment and Location okay. Wrong well number on sign (shows 236). NEED TO CORRECT WELL SIGN. 1st notice.						

CONE JALMAT YATES POOL UNIT No.741

G-25-22S-35E

30-025-33060-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
12/22/2010	Routine/Periodic	Mark Whitaker	Yes	No	1/31/2011	iMAW1035642015
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection: Equipment and Location okay. Wrong API # on well sign. NEED TO CORRECT WELL SIGN. 1st notice.						

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



015H14150977
HASLER
\$0.44
12/22/10
Mailed From 88240
US POSTAGE

MELROSE OPERATING COMPANY
ONE CHASEWOOD - SUITE 310
20333 CHASEWOOD PARK
HOUSTON, TX 77070