Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

## NM0321613


SUNDRY NOTICES AND REPORTS ON WELLS

OF THE PROPERTY OF THE PR

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No. South Mattix Unit Federal	
1. Type of Well  X Oil Well Gas Well Other  2. Name of Operator				8. Well Nam	
Occidental Permian Ltd.  3a. Address P.O. Box 50250, Midland, TX 79710-0250  4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2130 FNL 750 FEL SENE(H) Sec 15 T24S R37E		3b. Phone No. ( <i>include area code</i> ) 915-685-5717		9. API Well No. 30-025-35123 10. Field and Pool, or Exploratory Area Fowler Drinkard  11. County or Parish, State Lea NM	
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injecti	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Reclamation Recomplet	e ly Abandon	Water Shut-Off  X Well Integrity  Other
13. Describe Proposed or Completed Operation (clearly If the proposal is to deepen directionally or recompl Attach the Bond under which the work will be perf following completion of the involved operations. If testing has been completed. Final Abandonment N determined that the final site is ready for final inspector of the involved operation of the involved operations. If the complete is ready for final inspector of the involved operation operation of the involved operation o	ete horizontally, give some or provide the of the operation results in the operation results in the operation.)	subsurface locations and meas Bond No. on file with BLM/ n a multiple completion or re nly after all requirements, inc	sured and true ver BIA. Required su completion in a reluding reclamation	tical depths of a absequent reporties interval, a F on, have been c	all pertinent markers and zones; ts shall be filed within 30 days form 3160-4 shall be filed once ompleted, and the operator has
TD-6500' PBTD-6452' Perfs-	-6182-6292 <b>'</b>				
1. RIH & POOH w/ rods, pump and th	og, RIH and set	CIBP @ +/- 6132'			
2. Notify BLM/NMOCD of casing inte	egrity test 24h	rs in advance.			
<ol><li>RU pump truck, circulate well well</li></ol>	with treated wa	ter, pressure test	casing to 5	00 psi for	30 min and TA
	ATTACHEL				
Last grad 9/09 CON	DITIONS O	F APPROVAL			
14. I hereby certify that the foregoing is true and correct Name ( <i>PrintedTyped</i> )  David Stewart		Title Sr. Rec	gulatory Ana	ilvst	
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	Data	Data			
THIS	SPACE FOR FFD	ERAL OR STATE OFF			
Approved by /s/ JD Whitlock		Title [PE]		D	ate /2 /
Conditions of approval, if any, are attached Approval of	this notice does not w	arrant or Office			12/14/10
certify that the applicant holds legal or equitable title to the	nose rights in the subj	ect lease (Fo			

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Occidental Permian Ltd. - Current South Mattix Unit Federal #46 API No. 30-025-35123



11" hole @ 1100' 8-5/8" csg @ 1100' w/ 500sx-TOC-Surf-Circ


7-7/8" hole @ 6500' 5-1/2" csg @ 6500' DVT @ 3491' 1st w/ 500sx-TOC-3486'-Circ 2nd w/ 1000sx-TOC-Surf-Circ

Perfs @ 6182-6292'

2-7/8" tbg @ 6422' w/ TAC @ 6097'

PBTD-6452'

∠ Occidental Permian Ltd. - Proposed South Mattix Unit Federal #46 API No. 30-025-35123



11" hole @ 1100' 8-5/8" csg @ 1100' w/ 500sx-TOC-Surf-Circ

7-7/8" hole @ 6500' 5-1/2" csg @ 6500' DVT @ 3491' 1st w/ 500sx-TOC-3486'-Circ 2nd w/ 1000sx-TOC-Surf-Circ

Perfs @ 6182-6292'

CIBP @ 6132'

PBTD-6452'

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- Provides justification why the well should be temporarily abandoned rather than
  permanently plugged and abandoned and an estimated date that the well will be returned
  to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore</u> <u>diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

South Mattix Unit Fed. #46 Well may be approved to be TA/SI for a period of 90 days or until 3/16/2011 after successful MIT and subsequent report with well bore diagram is submitted. This will be the only TA approval for this well. Well must be returned to production, beneficial use or plans to P&A must be submitted by March 16, 2011.