

Submit 1 Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

RECEIVED JAN 06 2011 HOBSOCD		OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-04018
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			5. Indicate Type of Lease STATE ☒ FEE ☐
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐			6. State Oil & Gas Lease No.
2. Name of Operator Rhombus Operating Co., Ltd.			7. Lease Name or Unit Agreement Name Northwest Eumont Unit
3. Address of Operator P.O. Box 8316 midland, Tx 79708-8316			8. Well Number 117
4. Well Location Unit Letter P : 660 feet from the South line and 660 feet from the East line Section 15 Township 19S Range 36E NMPM County Lea			9. OGRID Number 19111
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3744 GL 3756 HB			10. Pool name or Wildcat Eumont Yates 7 Rvrs Queen

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: **TA** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. 12/17/10 - Set CIBP @ 4052' (top ref @ 4102') dump bail 35' limit on top of plug. New PBTD @ 4017'.
2. 12/18/10 - Circ well w/100 bbls 8kr fluid. Test to 500#. OK. LD +bs. Test to 500#. OK.
3. 1/4/11 - Conduct T/A status Test w/OCD per Mark Whitaker present. Press to 580#, held for 30 min w/no leakoff or gain. Test Good. Chart Attached


Spud Date:

Rig Release Date:

This Approval of Temporary Abandonment Expires **7-4-2011**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE **Tony Bunch** TITLE **Operations Manager** DATE **1/5/11**
Type or print name **Tony Bunch** E-mail address: **t48bunch@yahoo.com** PHONE: **575-370-4313**
For State Use Only
APPROVED BY: **[Signature]** TITLE **STAFF MGR** DATE **1-10-2011**
Conditions of Approval (if any):



Test Date
01-04-2011

BR 2221

GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CALB
10-2010
M&S Service

Rhombus Operating Co. LD
NW Eymont Unit # 117
30-025-04018
ULP Sec 15, T195, R362
Status Test

RECEIVED

JAN 06 2011

HOBBSOCD