RECEIVED

JAN 1 2 2011

Submit One Copy To Appropriate District Office District I HOBBSOCD State of New Mexico New Mexico New Mexico New Mexico New Mexico New Mexico	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-025-05195
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	T. D. Pope 35
1. Type of Well: XOil Well Gas Well Other	8. Well Number 21
2. Name of Operator Celero Energy II, LP	9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701	10. Pool name or Wildcat Denton; Devonian
4. Well Location Unit Letter A: 660 feet from the North line and 660 feet from the East line	
Section 35 — Township 14S Range 37E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON	
OTHER: Discretion Discreti	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE Lia Turt TITLE Regulatory Analyst	DATE 12/22/2010
TYPE OR PRINT NAME Lisa Hunt E-MAIL: lhunt@celeroener	gy.com PHONE: (432)686-1883
For State Use Only	
APPROVED BY: TITLE COMPLIANCE Conditions of Approval (if any)	Déces DATE 1/12/2011
▼	