RECEIVED

FFR 07 2011

LED O 1 For	
Submit One Copy To Appropriate Pipt BSSUUD State of New Mexico Office	Form C-103 January 20, 2011
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-01255
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	101091-001
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Michel
1. Type of Well: Soil Well Gas Well Other	8. Well Number 1
2. Name of Operator	9. OGRID Number
Southwest Royalties, Inc.	21355 10. Pool name or Wildcat
3. Address of Operator 6 Desta Drive, Ste 2100, Midland, Texas 79705	Sombrero Morrow
4. Well Location	
Unit Letter C: 660 feet from the N line and 1979 feet from the W line	
Section 13 Township 16S Range 33E NMPM Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	County <u>NM</u>
4170'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	1
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	T JOB
OTHER:	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Ope	rator's pit permit and closure plan.
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	nuction equipment and junk have been removed
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service	
company equipment, has been removed from lease and well location.	
When all work has been completed, return this form to the appropriate District office to sch	redule an inspection.
SIGNATURE Operations A	Assistant DATE _2/2/11
TYPE OR PRINT NAMEDawn M. HowardE-MAIL: _dhoward@claytonwilliams.comPHONE: _432/688-3267	
For State Use Only	
APPROVED BY: Mary Brown TITLE Compliance Office DATE 02/07/20/ Conditions of Approval (if any):	
Conditions of Approval (if any):	
→	-