

Submit 1 Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87401
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
FEB 10 2011
HOBBSOCD

State of New Mexico
Department of Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-20754
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Nordstrand Engineering Inc.		6. State Oil & Gas Lease No. L-5119
3. Address of Operator 3229 D' Amico Street Suite 200, Houston Texas 77019		7. Lease Name or Unit Agreement Name Western Holly "32" State
4. Well Location Unit Letter <u>B</u> : <u>990</u> feet from the North line and <u>1650</u> feet from the East line Section <u>32</u> Township <u>07S</u> Range <u>31E</u> NMPM County <u>Chaves</u>		8. Well Number <u>2</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4286 GL		9. OGRID Number 230757
		10. Pool name or Wildcat Tom-Tom (San Andres)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Repair work to bring the well back into production

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

After the well was purchased an inspection was conducted and it was determined that the tubing and the down hole pump had been removed. As a result of the missing equipment the well was off production.

Tubing was replaced in the well as was a new down hole pump and all other appropriate repairs made. The well was brought back in production October or November 2010. The repairs that were made were made in accordance with OCD guidelines and generally accepted industry practices. Tubing installed is 2-3/8" J-55.

The well is now in production.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Field Representative

DATE 2/2/2011

Type or print name Thomas E. Nordstrand E-mail address: tom@nmnvi.com PHONE: 505-321-7671 or 713-520-1555

For State Use Only

APPROVED BY:

TITLE

PETROLEUM ENGINEER

DATE

FEB 10 2011

Conditions of Approval (if any):